

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-10258

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
1964 P&A

Lease Name or Unit Agreement Name
Harris State

8. Well Number 1

9. OGRID Number
226685

10. Pool name or Wildcat
Antelope Sink (Upper Penn)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other Re-entry of P&A well ☐

2. Name of Operator
Sandel Operating Company

3. Address of Operator
P. O. Box 10487, Midland Texas 79702

4. Well Location
Unit Letter P : 660 feet from the South line and 660 feet from the East line
Section 36 Township 18S Range 23E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3830' KB

Pit or Below-grade Tank Application ☐ or Closure ☐ See C-144

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The well was plugged and abandoned beginning July 27, 2006.

First plug: 4700' - 4860': 30 sks with 3% S1(100#), H2O 4 barrels.
1 barrel FW, 7 barrels cement, 1 barrel FW and 26 barrels mud, Tagged at 4840'

Second plug: 3465' - 3615': 30 sacks with 3% S1 (100#), 4 barrels H2O
1 barrel fresh water 7 barrels cement, 1 barrel fresh water, and 18 barrels mud.

Third Plug: 1874' - 2024': 30 sacks with 3% S1 (100#), 4 barrels H2O
1 barrel fresh water 7 barrels cement, 1 barrel fresh water, and 8 barrels mud: Tagged at 1937'

Fourth plug: 1420' - 1535': 35 sacks with 3% S1 (100#), 5 barrels H2O
1 barrel fresh water 8 barrels cement, 1 barrel fresh water, and 6 barrels mud.

Fifth Plug: 525': 75 sacks with 3% S1 (200#), 11 barrels H2O Bring to Surface.

Sixth plug: Surface

Installed P&A Marker 08-02-06. Dug out cellar, cut off well head, trucked remaining fluid from reserve pit; finished clean of steel pits and graded location.
These plugging operations had Verbal approval from Van Barton on July 27th 2006.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Sheryl L. Jonas TITLE Agent for Sandel Operating DATE 08/08/06

Type or print name Sheryl L. Jonas
For State Use Only

E-mail address: Sjonas4011@aol.com Telephone No. 432-683-5511

APPROVED BY: _____
Conditions of Approval (if any):

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration, environmental remediation and final inspection is completed.

Accepted for record
Accepted
NMOCD