

WELL NAME AND NUMBER Artesia Unit #105

LOCATION Section 3 , T 18S,R28E. 1076 FSL, 789 FWL , Eddy County

OPERATOR Melrose Operating Company

DRILLING CONTRACTOR United Drilling, Inc.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and had conducted deviation test and obtained the following results:

<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>	<u>Degrees @ Depth</u>
<u>1 @ 460'</u>	<u> </u>	<u> </u>
<u>1/2 @ 1017'</u>	<u> </u>	<u> </u>
<u>1/4 @ 1520'</u>	<u> </u>	<u> </u>
<u>1/4 @ 2020'</u>	<u> </u>	<u> </u>
<u>1/2 @ 2549'</u>	<u> </u>	<u> </u>
<u>3/4 @ 3049'</u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

Drilling Contractor- UNITED DRILLING, INC.

By: *Luisa Garcia*
(Luisa Garcia)

Title: Assistant Office Manger

Subscribed and sworn to before me this 10 day of August, 2006.

Deery A. Chaves
Notary Public

My Commission Expires:

8-8-08

Chaves NM
County State