## District 1000 Robins Road, Aztec, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe office 077

Form C-144 June 1, 2004

1220 South St. Francis Dr. Santa Fe, NM 87505

Pit or Below-Grade Tank R		AMEND
	nk covered by a "general plan"? Yes X to below-grade tank Closure of a pit or below-	No Derade tank X
Type of action: Registration of a pit or below-grade tank Covered by a general plant if the X NO I Type of action: Registration of a pit or below-grade tank Closure of a pit or below-grade tank X  Decrator: SDX Resources, Inc. Telephone: 432/685-1761 e-mail address: _cmorgan@sdxresources.com  Address: _PO Box 5061, Midland, TX 79704		
'acility or well name: _Sedona #2API #: _30-015-34110U		
county: _Eddy 604' FSL 990' FEL Longitude	NAD: 1927 🗌 1983 🗍 Surface Ow	mer Federal State X Private Indian
<u>'ii</u>	Below-grade tank	
ype: Drilling X Production Disposal	Volume:bbl Type of fluid:	
Workover    Emergency	Construction material:	
ined X Unlined		
iner type: Synthetic X Thickness 12 mil Clay		
'it Volume _8000bbl		
Depth to ground water (vertical distance from bottom of pit to seasonal high vater elevation of ground water.)	Less than 50 feet	(20 points)
	50 feet or more, but less than 100 feet	(10 points)
	100 feet or more	( 0 points) 0
U. W	Yes	(20 points)
Vellhead protection area: (Less than 200 feet from a private domestic	No	( 0 points) 0
rater source, or less than 1000 feet from all other water sources.)		
Distance to surface water: (horizontal distance to all wetlands, playas, rigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet	(20 points)
	200 feet or more, but less than 1000 feet	(10 points)
	1000 feet or more	( 0 points) 0
	Ranking Score (Total Points)	0
If this is a pit closure: (1) attach a diagram of the facility showing the pit's representation start date and end date. (4) Groundwater encountered: No X Yes soil sample results and a diagram of sample locations and excavations.	. (3) Attach a general des	cription of remedial action taken including
Additional Comments: Mixed pit contents with earthen material. Dug & line	d an encapsulation pit (within the existing reserve as	rea) with a 12 mil synthetic liner.
Placed mixed contents in encapsulation pit. Capped with 20 mil synthetic liner		wy view w 12 1111 by milete 11101.
1 faced mixed contents in cheapstration pic. capped with 20 min syndrone mass	to covered chaire area wiar 5 clean top son.	
PICTURES ON FILE	***	
I hereby certify that the information above is true and complete to the best of n been/will be constructed or closed according to NMOCD guidelines X, a Date: 12/4/06		
Printed Name/TitleChuck Morgan, Engineer	Signature h	
Your certification and NMOCD approval of this application/closure does not otherwise endanger public health or the environment. Nor does it relieve the oregulations.	perator of its responsibility for compliance with any	
Approval: Sem W. Brenn	,	. ,
Approval: Printed Name/Title Wishiel II Sesses	Signature	Date: 12/7/66