rench Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 1000 Rio Brazes Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

Approval: Date: 12 Printed Name/Title

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

March 12, 2004 For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe

Form C-144

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes No

Type of action: Registration of a pit or below-grade tank \(\subseteq\) Closure of a pit or below-grade tank

Operator: Marbob Energy Corporation Telephone: 505-748-3303 e-mail address: marbob@marbob.com Address: PO Box 227, Artesia, NM 88211-0227 255' FNL & 330' FEL Facility or well name: Dodd Federal Unit #105 API#: 30-015-34562 U/L or Otr/Otr NENE Sec 14 T 17S R 29E County: Eddy Latitude Longitude NAD: 1927 ☐ 1983 ☐ Surface Owner Federal ☒ State ☐ Private ☐ Indian ☐ Pit Below-grade tank Type: Drilling Production Disposal Volume: _bbl Type of fluid: ___ Construction material: Lined Unlined Double-walled, with leak detection? Yes If not, explain why not. Liner type: Synthetic

☐ Thickness 12 mil Clay ☐ Volume Less than 50 feet (20 points) Depth to ground water (vertical distance from bottom of pit to seasonal high (10 points) 50 feet or more, but less than 100 feet water elevation of ground water.) 100 feet or more 0 points (0 points) (20 points) Yes Wellhead protection area: (Less than 200 feet from a private domestic No 0 points (0 points) water source, or less than 1000 feet from all other water sources.) Less than 200 feet (20 points) Distance to surface water: (horizontal distance to all wetlands, playas, (10 points) 200 feet or more, but less than 1000 feet irrigation canals, ditches, and perennial and ephemeral watercourses.) 1000 feet or more (0 points) 0 points Ranking Score (Total Points) 0 points If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: onsite offsite from If offsite, name of facility _. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No 🗌 Yes 🔲 If yes, show depth below ground surface ________ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit ☒, or an (attached) alternative OCD-approved plan □. Date: December 6, 2006 **Gerald Herrera** Printed Name/Title: Signature Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations Victorial II Sepervisor

Signature

Marbob Energy Corporation Attachment to OCD Form C-144


Pit or Below-Grade Tank Registration or Closure

Pi	t	C	losi	ш	re
	L	_	-	_	

Dodd Federal Unit #105

255' FNL & 330' FEL Section 14 T-17S R-29E Eddy County, New Mexico

(1) Facility diagram



(2) Disposal location:

Fluids will be disposed at an approved disposal facility.

(3) General description of remedial action:

Transfer cuttings to ends, dig deep bury pit in center of pit, line with 12 mil plastic. Use material to stiffen cuttings. Transfer stiffened cuttings into lined pits, leaving mounded for drainage. Cap with 20 mil liner. Cover with three feet of cover material.

(4) Groundwater encountered:

No

(5) Soil sample:

N/A