

30-015-35257

Summary Report

Dorsey Rogers
Cimarex
207 S Mesa
Carlsbad, NM, 88220

Report Date: January 4, 2007

Work Order: 7010407

Project Location: Sec 33-T175-R30E Eddy County,NM
Project Name: Full Tank 33 Fed 3Y

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
113039	Bkg North	soil	2007-01-03	13:35	2007-01-04
113040	Bkg South	soil	2007-01-03	13:15	2007-01-04
113041	Bkg East	soil	2007-01-03	13:45	2007-01-04
113042	Bkg West	soil	2007-01-03	13:25	2007-01-04

Sample: 113039 - Bkg North

Param	Flag	Result	Units	RL
Chloride		26.7	mg/Kg	2.00

Sample: 113040 - Bkg South

Param	Flag	Result	Units	RL
Chloride		<4.00	mg/Kg	2.00

Sample: 113041 - Bkg East

Param	Flag	Result	Units	RL
Chloride		<4.00	mg/Kg	2.00

Sample: 113042 - Bkg West

Param	Flag	Result	Units	RL
Chloride		73.3	mg/Kg	2.00

Summary Report

Dorsey Rogers
Cimarex
207 S Mesa
Carlsbad, NM, 88220

Report Date: January 4, 2007

Work Order: 7010408



Project Location: Sec 33-T175-R30E Eddy County,NM
Project Name: Full Tank 33 Fed 3Y

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
113043	Bkg North	soil	2007-01-03	14:15	2007-01-04
113044	Bkg South	soil	2007-01-03	14:35	2007-01-04
113045	Bkg East	soil	2007-01-03	14:25	2007-01-04
113046	Bkg West	soil	2007-01-03	14:45	2007-01-04

Sample: 113043 - Bkg North

Param	Flag	Result	Units	RL
Chloride		<4.00	mg/Kg	2.00

Sample: 113044 - Bkg South

Param	Flag	Result	Units	RL
Chloride		<4.00	mg/Kg	2.00

Sample: 113045 - Bkg East

Param	Flag	Result	Units	RL
Chloride		<4.00	mg/Kg	2.00

Sample: 113046 - Bkg West

Param	Flag	Result	Units	RL
Chloride		<4.00	mg/Kg	2.00