



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary


**Mark E. Fesmire, P.E.**

Director

Oil Conservation Division

December 7, 2006

Nordstrand Engineering Inc.  
3229 D'Amico St. #200  
Houston, TX 77019



*No Release.  
Pump Jack, Max.  
Pipes & Sank on back  
P/A marker not used!*

Form C-103 Report of Plugging for your

| API WELL #   | Well Name              | Well # |
|--------------|------------------------|--------|
| 30-015-03818 | W. Henshaw Premier Ut. | 1      |

has been received and approved pending final notice of final inspection. Bond cannot be released until an NMOC representative has made an inspection of the location and found it to be in compliance with OCD rules and regulations. **Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.**

- ☒ 1. All pits have been filled and leveled in accordance with Rule 50. *OK*
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed. *OK*
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment. *N/A*
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

**When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to the OCD Artesia District Office.**

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval

Name

*Carl B. Sandstrom*

*President*  
Title

*Gerry Guye*  
Gerry Guye  
Deputy Field Inspector

*P/A marker  
in place. but  
not in concrete  
or welded to CSC.  
CMT. 4' from  
top of CSC.*

*1/3/07  
PL*

# Memo

**To:** File  
**From:** Gerry Guye  
**CC:** [Click [here](#) and type name]  
**Date:** 1/4/2007  
**Re:** West Henshaw Premier Unit # 1 and ! N

---

I called Carl Nordstrand and asked him to complete the plugging on these wells. He told me he would contact the plugging company and get them right on it.

A handwritten signature in black ink, appearing to be 'G. Guye', is written over the memo text.