Submit 3 Copies To Appropriate District 2223242526 State of New Mexico	F C 102
	Form C-103
District I Provide Dr. Hobbs NIM 88500	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240  District II  1301 W. Grand Ave., Artesia, NM 88210  District II  CONSERVATION DIVISION	30-015-00290
	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410	STATE ☐ FEE ⊠
District IV Sama Fe, NW 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
SUNDRY NOTITIES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TENT BACK TO A	Atoka San Andres Unit
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TEXT BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C 100) FOR SUDI PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	151
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, LP	6137 10. Pool name or Wildcat
3. Address of Operator 20 North Broadway, Oklahoma City, OK 73102-8260 (405) 552-8198	San Andres
4. Well Location (403) 332-8138	San Andres
Unit Letter M : 990 feet from the South line and 330 feet from the West line	
Section 13 Township 18S Range 26E  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM County Eddy
3315' KB	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check rippropriate Box to indicate retained, report of other Bata	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	
PULL OR ALTER CASING	
OTHER:   OTHER: TA STATUS	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
A successful Machaniaal Integrity Test was performed on the referenced well on 12	/21/06 and the original chart was retained
A successful Mechanical Integrity Test was performed on the referenced well on 12/21/06 and the original chart was retained by the NM OCD, District II. A CIBP was set 1570'.	
, mo . m. 000, 200 m	
This well is in our waterflood area. The well therefore has utility should additional in	
and flooded. As the ASAU is expected to produce for quite some time, the potentia	
ongoing. As this situation is not expected to change, we are requesting a longer ter	m temporary abandonment status.
Temporary Abandoned StatusApproved	
Until (2-2	
VIIII 10	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief. I further certify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .	
SIGNATURE TITLE Sr. Staff Engineerin	Tooknision DATE 1/22/06
SIGNATORE Sr. Stan Engineerin	g TechnicianDATE_1/23/06
Type or print name Norvella Adams E-mail address: norvella.adams@dvn.com Telephone No. (405) 552-8198	
For State Use Only Geny Guye	
1 1111 turn	<b>coector</b>
**************************************	DATEAN 3 1 2007
Conditions of Approval (if any):	