

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-05-33611

## Release Notification and Corrective Action

nmlb070573271

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company OXY USA	Contact Rick Kerby
Address 102 S. Main St. PO Box 1988 Carlsbad, NM 88220	Telephone No. (O) 505-887-8337 C) 505-631-4972
Facility Name OXY McKittrick 11-5 SWD	Facility Type SWD Battery

Surface Owner BLM	Mineral Owner	Lease No.
-------------------	---------------	-----------

## LOCATION OF RELEASE

Unit Lotter L	Section 11	Township 22S	Range 24R	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
---------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	-------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release Produced fluids	Volume of Release 260 BBL	Volume Recovered 250 BBL
Source of Release Produced water tank	Date and Hour of Occurrence 5:00 AM 2-22-07	Date and Hour of Discovery 7:00 AM 2-22-07
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Notification rec'd 2/23/07	
By Whom?	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Valve left closed and ran over water tank. Fluids picked up and disposed. Will let dry and remove contaminated dirt. This is an active location and further remediation will be considered on removal of contaminated soil.

Describe Area Affected and Cleanup Action Taken.\*

All fluid remained inside of diked area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Rick Kerby	OIL CONSERVATION DIVISION	
Printed Name: Rick Kerby	TIM GUM by MB	
Title: HES Tech	Approved by District Supervisor:	Approval Date: FEB 26 2007 Expiration Date:
E-mail Address: rick.kerby@oxy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: Phone: 505-631-4972		

\* Attach Additional Sheets If Necessary