

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REC'D O&D Dist II
4/17/07
PAB

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27548

Release Notification and Corrective Action

nLLB 07155-40865

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Pogo Producing Company	Contact: Pat Ellis
Address: P.O. Box 10340 Midland, Texas 79702	Telephone No. (432) 685-8100
Facility Name: Sand Dunes 34 Federal #8	Facility Type: Well Head

Surface Owner	Mineral Owner	Lease No. NM-43744
---------------	---------------	--------------------

LOCATION OF RELEASE

Unit Letter O	Section\ 34	Township 23S	Range 31E	Feet from the 330'	North/South Line South Line	Feet from the 1980'	East/West Line East	County Eddy
------------------	----------------	-----------------	--------------	-----------------------	--------------------------------	------------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil/Water	Volume of Release 15 BBLs	Volume Recovered 10 bbls
Source of Release Stuffing Box Leak	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 12/28/06 at 4:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Answering Automated Service	
By Whom? Patrick Ellis	Date and Hour 12/28/06 6:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
None

Describe Cause of Problem and Remedial Action Taken.*
A valve was closed on wellhead causing stuffing box to pressure up and leak. The valve was opened and stuffing box repaired.

Describe Area Affected and Cleanup Action Taken.*
The area affected included well pad and small area of pasture. All free fluids were removed by vacuum truck. Highlander Environmental performed assessment on property in January and site was excavated and impacted soils transported offsite for disposal in March 2007.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patrick L. Ellis</i>	OIL CONSERVATION DIVISION	
Printed Name: Patrick L. Ellis	Approved by District Supervisor: TIM GUM by MB <i>Mike Gumm</i>	
Title: Environmental Health and Safety Supervisor	Approval Date: 4/16/07	Expiration Date:
E-mail Address: ellisp@pogoproducing.com	Conditions of Approval: <i>Final Report on File</i>	Attached <input type="checkbox"/>
Date: 4/5/07 Phone: (432) 685-8148		

Attach Additional Sheets If Necessary