<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe

Form C-144 June 1, 2004

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes \(\subseteq \text{No \(\mathbb{X} \)} \)

Type of action: Registration of a pit or below-grade tank \(\subseteq \) Closure of a pit or below-grade tank \(\subseteq \)

Operator: CHESAPEAKE OPERATING. INC. Telephon	e: 432-687-2992 e-mail address: SS	TRICKLIN@CHKENERGY.CO		
Address. P. O. BOX 11050 MIDLAND, TEXAS 79702-8050				
	0-015-23674 U/L or Qtr/Qtr G			
County: EDDY Latitude _	Longitude	NAD: 1927 ☐ 1983 ☐		
Surface Owner: Federal 🗌 State 🔲 Private 🔀 Indian 🗍				
Pit	Below-grade tank			
Type. Drilling X Production Disposal	Volume:bbl Type of fluid:			
Workover ☐ Emergency ☐	Construction material:			
Lined 🔀 Unlined 🗌	Double-walled, with leak detection? Yes If not, explain why not.			
Liner type: Synthetic 🛛 Thickness 12 mil Clay 🗌				
Pit Volume <u>12,139</u> bbl				
Depth to ground water (vertical distance from bottom of pit to seasonal				
high water elevation of ground water.)	Less than 50 feet	(20 points)		
200'+	50 feet or more, but less than 100 feet	(10 points)		
	100 feet or more	(0 points) 0		
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)		
water source, or less than 1000 feet from all other water sources.)	No	(0 points) 0		
Distance to surface water: (horizontal distance to all wetlands, playas,	110	(o points)		
irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet	(20 points)		
inigation canais, diteries, and perenniar and epitemeral watercourses.)	200 feet or more, but less than 1000 feet	(10 points)		
	1000 feet or more	(0 points) 0		
	Ranking Score (Total Points)	0		
If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if				
your are burying in place) onsite 🔲 offsite 🔲 If offsite, name of facility (3) Attach a general description of remedial action taken including				
remediation start date and end date. (4) Groundwater encountered. No 🛛 Yes 🔲 If yes, show depth below ground surfaceft. and attach sample results.				
(5) Attach soil sample results and a diagram of sample locations and excavations.				
Additional Comments:				
A SIDE DEEP BURIAL TRENCH WAS EXCAVATED NEXT TO THE PIT. THE TRENCH WAS LINED WITH A 20 MIL SYNTETIC LINER. THE				
PIT CONTENTS WERE THEN PLACED INTO THE LINED TRENCH. THE SIDES OF THE TRENCH WERE FOLDED OVER THE CONTENTS AND A TOP COVER OF 20 MIL SYNTHETIC LINER WAS SEWED IN PLACE. THREE FEET OF TOP SOIL WAS PLACED ON TOP OF THE				
LINED TRENCH AND COMPACTED. THE ORIGINAL PIT WAS BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO				
GRADE. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED. THE PIT				
CLOSURE WAS STARTED ON APRIL 23, 2007 AND COMPLETED ON MAY 18, 2007.				
I hereby certify that the information above is true and complete to the best has been/will be constructed or closed according to NMOCD guideline	of my knowledge and belief. I further certify that	the above-described pit or below-grade tank		
has been/will be constructed or closed according to NMOCD guidelines 🖾, a general permit 🗔, or an (attached) alternative OCD-approved plan 🗖.				
Date. 6/20/07				
CLIFF BRUNSON, PRESIDENT, BBC INTL	Signature_Cliff P. Tunan FO			
Printed Name/Title	Signature_Signature_FO	R CHESAPEAKE OPERATING, INC		
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or				
otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or.				
Approval:	Accepted for reco	ra MB		
Printed Name/Title	Signature	Date: JUN 2 6 2007		



PHONE (325) 673-7001 - 2111 BEECHWOOD - ABILENE, TX 79603

PHONE (505) 393-2326 . 101 E MARLAND . HOBBS, NM 88240

ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O. BOX 805 HOBBS, NM 88241 FAX TO: (505) 397-0397

Receiving Date: 05/07/07

Reporting Date: 05/08/07 Project Owner: NOT GIVEN

Project Name: FLOYD R1 COM1

Project Location: CARLSBAD, NM

Analysis Date: 05/08/07 Sampling Date: 05/07/07

Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: AB

Analyzed By: AB

LAB NUMBER SAMPLE ID C (mg/Kg)

H12565-1 PIT COMPOSITE	32
Quality Central	500
Quality Control	500
True Value QC	500
% Recovery	. 100
Relative Percent Difference	1.0

SECTION. Classifications	4500-CFB
METHOD: Standard Methods	4300-010

Note: Analysis performed on a 1:4 w:v aqueous extract,

Chemist

Date

H12565

PLEASE NOTE: Liability and Dameges. Cardinal's liability and chern's exclusive remedy for any claim arising, whether based in contract or loft, shall be limited to the emount peid by chern for an alyest an element. Including those for negligence and any other cause what over shall be deemed waived unless made in willing and received by Cardinal within thirty (30) days after complation of the applicable service. In no event attal Cardinal be liable for incidental or consequential demages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

ARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM B8240 (915) 673-7001 Fax (916) 673-7020 (505) 393-2326 Fax (605) 393-2478 Company Name: BBC International Inc. BILL TO ANALYSIS REQUES Project Manager Cliff Brunson P.O. #: P.O. Box 805 Company: State: NA Zip: 8824/ Altn: Phone = 505-397-6388 Fax # 505- 397-0397 Address: Project Owner: City: Project #. Floya RI Com ! State: 2jp: Project Hame: Carlshad, Non Phone #: Project Location: Cliff Brunson Fax #: Sampler Hame: HATRIX PRESERY. SAMPLING FOR LIGHTS CHLY 4100,00 (G)RAB OR (C)OMP GROUNDWATER
WASTEWATER
SOIL
GRUDE OIL
SLUGGE
OTHER:
ACIDIBASE:
ICE / CDOL Sample I.D. Lab I.D. DATE Pit Compesite 5/7/97 9:00 A H12565-Where push that at the rade of 20th per service bears the articles had at France, and of speet of substatute, had not attended to form. ANY 2 AND GLOS OF PARKET HE SEE CONTINUES OF SEPTICES FOR CONTINUES OF CONTINUES OF SEPTICES AND AND AND ADDRESS OF SEPTIMES O Phone Result Yes DNo Add Phone \$ Received By: Sampler Relinguished: Fax Rough: □ Yes □ No |Add'| Fax #: REMARKS: CHECKED ON Cool Intact [init|els] ismaler - UPS - Bus - Other:

[†] Cardinal cannot accept verbal changes. Plesse fax written changes to 605-393-2476.