

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

API# 30-015-35496
nLLB0716549732

Release Notification and Corrective Action

06R0711158

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Permian Drilling	Contact	Chuck Landrum
Address	814 W. Marland Blvd., Hobbs, NM 88240	Telephone No.	(505) 441-3715
Facility Name	J. C. Williamson - Ross Draw #25	Facility Type	Well
Surface Owner:	J. C. Williamson	Mineral Owner:	Federal
		Lease No.	NM 0554499
		API No.	30-015-35496

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	26	26S	30E	2336	South	1831	West	Eddy

Latitude N 32 deg. 0.745.1' Longitude W 103 deg. 51 240.5'

NATURE OF RELEASE

Type of Release	Diesel	Volume of Release	25 bbl	Volume Recovered	None
Source of Release	Day Tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	4/26/07
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (OCD - Artesia), Jim Amos (BLM - Carlsbad)			
By Whom?	Cindy Crain (Ocotillo Environmental)	Date and Hour 4/30/07 (0800)			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Diesel was released from a day tank due to a stuck float in the tank. No remediation has occurred at this time

Describe Area Affected and Cleanup Action Taken.*

Area is approximately 30' x 35' on the well pad, and 240' x 2' off site. Surficially impacted soil will be removed to an NMOCD approved disposal facility. Horizontal and vertical delineation of the spill will be conducted and soil will be remediated to OCD and/or BLM requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chuck Landrum	Approved by District Supervisor: TIM GUM by MB 	
Title: Safety Director/Human Resources/Training	Approval Date: 6/14/07	Expiration Date:
E-mail Address: chucklandrum@valornet.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 4/30/07 Phone: (505) 441-3715		

* Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

June 14, 2007

Permian Drilling Company
814 W. Marland Blvd
Hobbs, NM 88240
ATTN: Environmental Department

Reference **JC Williamson-Ross Draw #25 26-26S-30E API # 30-015-35496 Eddy County, New Mexico**

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 reporting a release of produced fluids that occurred on or about April 30, 2007 at the above referenced well site. Please submit a work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD Rules and Guidelines.

A publication outlining OCD guidelines and requirements for site ranking and spill remediation can be found on the OCD website as follows: <http://www.emnrd.state.nm.us/ocd> Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 office no later than Sept. 14, 2007. Please include any remedial or clean up actions that have already been performed.

Remediation requirements may be subject to other federal, state, local laws and/or regulations.

If I can be of assistance in this matter, my contact information is listed below.

Sincerely,

Mike Bratcher
NMOCD District 2
1301 W. Grand Ave.
Artesia, NM 88210
(505) 748-1283 Ext. 108
(505) 626-0857
mikc.bratcher@state.nm.us

Tracking number: nLLB0716549732