District I 1625 N French Dr., Hobbs, NM 88240 District if 1301 W Grand Avenue, A District III District III 1000 Rio Brazos Road, Aztec, NM:87410 District IV 1220 S St. Francis Dr., Santa Ec., NM:87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 June 1, 2004 For drilling and production facilities, submit to appropriate NMOCD District Office. For downstream facilities, submit to Santa Fe

office

Pit or Below-Grade Tank Registration or Closure Is nit or below-grade tank covered by a "general plan"? Yes No Submitted 4/16/04

	505-622-4795 e-mail addressjennifer@mcka	ade tank ayoul com	AUG 03 2007 OCD-ARTESIA
Address PO Box 2014 Roswell, NM 88202-2014	12 - 22		OCD-ARTEON
Facility or well name. LL&E B Federal #3 AP 30 - COS-			
County <u>CHAVES</u> Latitude Longitude	NAD: 1927 🗌 1983 🗎 Surface	Owner Federal 🗵	State Private Indian
Pit	Below-grade tank		
Type Drilling ☑ Production ☐ Disposal ☐	Volumebbl Type of fluid:		 _
Workover	Construction material		
Lined ☑ Unlined □	Double-walled, with leak detection? Yes If	not, explain why	not.
Liner type. Synthetic Thickness 12 mil Clay Pit Volume bbl		· · · · · · · · · · · · · · · · · · ·	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet	(20 points)	
	50 feet or more, but less than 100 feet	(10 points)	
	100 feet or more	(0 points)	
Wellhead protection area (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources)	Yes	(20 points)	
	No No	(0 points)	
Distance to surface water (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses)	Less than 200 feet	(20 points)	
	200 feet or more, but less than 1000 feet	(10 points)	
	1000 feet or more	(0 points)	1
	Ranking Score (Total Points)	0	
		ft an	
Attach soil sample results and a diagram of sample locations and excavations.	☐ If yes, show depth below ground surface		•
remediation start date and end date (4) Groundwater encountered No 🛛 Yes Attach soil sample results and a diagram of sample locations and excavations. Additional Comments. A plan of reserve pit remediation is attached			•
Attach soil sample results and a diagram of sample locations and excavations.			•
Attach soil sample results and a diagram of sample locations and excavations. Additional Comments. A plan of reserve pit remediation is attached. Thereby certify that the information above is true and complete to the best of been/will be constructed or closed according to NMOCD guidelines, a general complete to the best of the been according to NMOCD guidelines.	ny knowledge and belief I further certify that	the above-descri	bed pit or below-grade tank
Attach soil sample results and a diagram of sample locations and excavations. Additional Comments. A plan of reserve pit remediation is attached Thereby certify that the information above is true and complete to the best of inbeen/will be constructed or closed according to NMOCD guidelines, a given by the same of t	ny knowledge and belief I further certify that teneral permit [], or an (attached) alternative (the above-descri	bed pit or below-grade tank
Attach soil sample results and a diagram of sample locations and excavations. Additional Comments. A plan of reserve pit remediation is attached. Thereby certify that the information above is true and complete to the best of been/will be constructed or closed according to NMOCD guidelines, a general complete to the best of the been according to NMOCD guidelines.	my knowledge and belief I further certify that general permit, or an (attached) alternative of Signature.	the above-descri OCD-approved [bed pit or below-grade tank blan∐.
Additional Comments. A plan of reserve pit remediation is attached Thereby certify that the information above is true and complete to the best of inbeen/will be constructed or closed according to NMOCD guidelines, a grate 8/2/2007 Printed Name/Title James L. Schultz, Agent Your certification and NMOCD approval of this application/closure does not inotherwise endanger public health or the environment. Nor does it relieve the constructions.	my knowledge and belief I further certify that general permit, or an (attached) alternative of Signature.	the above-descri OCD-approved [bed pit or below-grade tank blan∐.

Reserve Pit Remediation Plan

LL&E B Federal #3 610'FNL & 1980'FEL Sec. 12, T6S, R22E

- 1. Collect soil samples from the walls of the reserve pit as shown on attached plat (from surface to depth reading 250 ppm chlorides).
- 2. Pile cuttings and original pit liner to one side of reserve pit.
- 3. Collect soil samples from inside the pit on the cleared side of reserve pit (trench area) at surface.
- 4. Dig trench in cleaned out side of the pit, big enough to put all of the cuttings in and leave enough room for 3' backfill material. (NOTE: Trench size depends on amount of cuttings, rock formations, surrounding terrain and mud solidity.)
- 5. Collect soil samples from inside trench area to a depth reading 250 ppm chloride.
- 6. Line trench with 20 MIL liner.
- 7. Fill the trench with cuttings and original pit liner.
- 8. Cap trench with 20 MIL liner.
- 9. Collect soil samples from points within the reserve pit (not including the trench area which were collected in Step 5) as shown on attached plat from surface to depth reading 250 ppm chlorides.
- 10. Back fill area (trench -3' and reserve pit -1') with topsoil.
- 11. Seed area per BLM specifications.

LL&E FEDERAL B #3 610' FNL AND 1980' FEL Sec. 12, T6S, R22E



