

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

AUG 13 2007
OCD-ARTESIA

Release Notification and Corrective Action

30-015-33928

OPERATOR

X Initial Report

Final Report

Name of Company	Range Operating New Mexico, Inc.	Contact	Linda C Stiles
Address	100 Throckmorton Street Suite 1200 Fort Worth TX 76102	Telephone No.	(817) 869-4208
Facility Name	Teledyne	Facility Type	Battery
Surface Owner	Intrepid Mining NM, LLC	Mineral Owner	United States of America Bureau of Land Management
		Lease No	3001533928

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	12	25S	37E	1980	SOUTH	990	WEST	Eddy

Latitude 32°19'05.44"N Longitude 104°02'44 69"W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	72	Volume Recovered	65
Source of		Date and Hour of Occurrence	8-8-07	Date and Hour of Discovery	8 00 AM 8-8-07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher (NMOCD) Jim Amus (BLM)		
		Date and Hour	8-9-07 2 00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	NA		
If a Watercourse was Impacted, Describe Fully *	NA				
Describe Cause of Problem and Remedial Action Taken *	Water Transfer Pump Malfunction (Electricity Wire Grounded Out) Water Tanks Ran Over. Spill was contained within the firewall				
Describe Area Affected and Cleanup Action Taken *	Water was contained inside firewalls Called vacuum truck (Key Trucking) Recovered 65 bbls and hauled to disposal				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations					
Signature	OIL CONSERVATION DIVISION				
Printed Name	Linda C Stiles	Approved by	District Supervisor. <i>[Signature]</i>		
Title	Sr Engineering Tech	Approval Date	8/16/07	Expiration Date	8/14/07
E-mail Address	lstiles@rangeresources.com	Conditions of Approval	Attached <input checked="" type="checkbox"/>		
Date	8-9-07	Phone	(817) 869-4208		

* Attach Additional Sheets If Necessary



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

August 16, 2007

Range Operating New Mexico, Inc.
100 Throckmorton Street, Suite 1200
Fort Worth, Texas 76102

ATTN: Linda C. Stiles

RE: Teledyne 12 Federal Battery (30-015-33928)

Dear Ms Stiles:

This office is in receipt of your C-141 on the produced water release, at this facility.

NMOCD Rule 19.15.3.116 states in part ... "The responsible person must complete division approved corrective action for releases which endanger public health or the environment. Releases will be addressed in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with Section 19 of 19.15.1 NMAC."

Information and tools for proper corrective action may be found in the Environmental Handbook on our web site www.emnrd.state.nm.us/ocd under the heading publications.

Remediation requirements may be subject to other federal, state and local laws or regulations.

Within 30 days, **on or before September 14, 2007**, completion of corrective activities should be finalized and a final report summarizing all actions taken to mitigate environmental damage related to the leak, spill or release will be provided to OCD for approval.

Please be advised that NMOCD acceptance and/or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If I may be of further service or if you have any questions please feel free to contact me.

Sincerely,

Gerry Guye
Deputy Field Inspector
NMOCD District II, Artesia
(505) 748-1283 ext 105
Cell (505) 626-0843
E-mail: gerry.guye@state.nm.us