

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



WELL API NO. 30-015-22634
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name: EMPIRE ABO UNIT 'H'
2. Name of Operator BP America Production Company	8. Well Number 303
3. Address of Operator P.O. Box 1089, Eunice NM 88231	9. OGRID Number 00778
4. Well Location Unit Letter <u>N</u> : <u>800</u> feet from the <u>S</u> line and <u>1340</u> feet from the <u>W</u> line Section <u>33</u> Township <u>17S</u> Range <u>28E</u> NMPM County <u>EDDY</u>	10. Pool name or Wildcat EMPIRE ABO
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3665.6' GR	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE ☐

FINAL T/A EXTENSION

OTHER: \_\_\_\_\_  
Date of Last Production 5/11/1986  
Well must be returned to beneficial use or a

13. Describe proper P/A plan submitted prior to 5/11/2008  
of starting any \_\_\_\_\_  
or recompleti \_\_\_\_\_

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: MIT ☒

pertinent details, and give pertinent dates, including estimated date of Completion: Attach wellbore diagram of proposed completion

TD: 6325' PBD: 6275' CIBP: 6180.11' PERFS: 6195' Pengo tool w/ sliding sleeve

11/1/07: MIT performed. Witnessed by Richard Inge of OCD. Test was successful and Mr. Inge retained the original chart.

BP America requests an extension of TA status to retain wellbore for future use and uphole potential.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Vicki Owens TITLE Administrative Assistant DATE 11/8/07

Type or print name Vicki Owens

E-mail address: vicki.owens@bp.com  
Telephone No. 505-394-1650

For State Use Only

APPROVED BY Richard Inge TITLE Compliance Officer DATE 11/29/07

Conditions of Approval, if any: