

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

nmlb0735449364

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report


Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 505-748-1471	
Facility Name Anemone ANE Federal #2	API Number 30-015-27982	Facility Type Battery
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-72814

LOCATION OF RELEASE

Unit Letter D	Section 9	Township 22S	Range 24E	Feet from the 1090	North/South Line North	Feet from the 840	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.40957 Longitude 104.50867

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 B/O	Volume Recovered 7 B/O
Source of Release Flow Line	Date and Hour of Occurrence 8/8/2006 - AM	Date and Hour of Discovery 8/8/2006 - AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Heater lost gas pressure; fluid from heater went into short tank and ran over. Spilled fluids from tank were contained within the berm, inside bermed area has a plastic liner, liner intact and fluids did not saturate soils below tank. Called Transvac truck.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 14' X 45'. Shut down heater and made repairs, vacuumed up standing fluids, flow line repaired, contaminated gravel removed/replaced. Depth to Ground Water: 50-99', Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Requesting final closure, based on amounts released/recovered and contained within bermed area with plastic liner.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCED rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCED marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCED acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: TIM GUM Signed By 	
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: boba@ypenm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Thursday, August 17, 2006	Phone: 505-748-1471	

* Attach Additional Sheets If Necessary