Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Offical L May 27, 2004 Energy, Minerals and Natural Resources WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-015-34929 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 VA-2600 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Manchester State Unit PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other JAN 02 2008 2. Name of Operator 9. OGRID Number Yates Petroleum Corporation 025575 OCU-AKIESIA 3. Address of Operator 10. Pool name or Wildcat 105 S. 4th Street, Artesia, NM 88210 Runyan Ranch; Morrow 4. Well Location Unit Letter 760 feet from the North line and 660 feet from the West line **NMPM** 20 19S Township 23E Eddy Section Range County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4062'GR Pit or Below-grade Tank Application or Closure Pit type ______ Depth to Groundwater _____ Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ П **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS.□ PLUG AND ABANDON ☐ MULTIPLE COMPL PULL OR ALTER CASING CASING/CEMENT JOB OTHER: OTHER: Unsuccessful Recompletion, Back to Morrow 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/17/07 - TOOH with production string. TIH with retrieving tool, 2-7/8" tubing and tag at 6495'. Circulated sand from 6495'-6505'. Release RBP at 6505'. TOOH with tubing and RBP. TIH with retrieving tool and 2-7/8" tubing and jay onto packer at 7243'. 12/19/07 - RECOMPLETION UNSUCCESSFUL, WELL IS BACK TO PRODUCING FROM MORROW PERFS 7572'-7584' I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines [, a general permit [] or an (attached) alternative OCD-approved plan []. SIGNATURE TITLE Regulatory Compliance Supervisor DATE December 26, 2007 Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471 For State Use Only APPROVED BY: DATE Conditions of Approval (if any): Accepted for record - NMOCD