Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

5 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM98122 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No NMNM71030A	
Type of Well					8. Well Name and No. SKELLY UNIT 74	
Name of Operator FOREST OIL CORPORATION	1	9. API Well No. 30-015-05331-00-S1				
3a Address 707 17TH STREET SUITE 36 DENVER, CO 80202	3b. Phone No. (include area code) Ph: 303-812-1554 Fx: 303-864-6105)	10. Field and Pool, or Exploratory GRAYBURG		
4. Location of Well (Footage, Sec., T, R., M., or Survey Description)					11. County or Parish, a	and State
Sec 21 T17S R31E SWSW 530FSL 330FWL			EDDY C			, NM
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF 1	NOTICE, R	EPORT, OR OTHER	R DATA
TYPE OF SUBMISSION '	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize☐ Alter Casing	□ Deep	pen ture Treat	☐ Production (Start/Resume		☐ Water Shut-Off☐ Well Integrity
Subsequent Report	Casing Repair	_	Construction	Recom		Other
☐ Final Abandonment Notice	☐ Change Plans	_	and Abandon		rarily Abandon	_
_	☐ Convert to Injection			— ', -		
13. Describe Proposed or Completed Ope If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final Aldetermined that the site is ready for for 11-7-07 Drove to location 11-8-07 RU PU ND WH, try to for gang to bring 25 jts 2 3/8" tag & lay down, on pipe rack. 11-9-07 Open well pick up 6" POH & lay down bit & scraper & add one jt went down to 145" tag @ 14/37" tongs started to	ally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be fill in the interest of the control of the cont	y give subsurface the Bond No. or esults in a multipled only after all in a 2 3/8 sub, No. on tag, POH	locations and measinal file with BLM/BI/e completion or recoverequirements, included by the BOP waited ag @ 1405'	A. Required su completion in a ding reclamation	ertical depths of all pertine bequent reports shall be new interval, a Form 3160 in, have been completed, a CCEPTED FOR RI	ent markers and zones. filed within 30 days 0-4 shall be filed once and the operator has
5' tag @ 1437' tongs started to 11-12-07 Knights Servcie set vaccum trk fill reverse pit, pick 6" 1/8, RIH w/39 jts 2-7/8 tag	reverse unit, reverse pit, up drill collars 4" 1/8 & c	drill bit	ollars,	NM(ry Guye, Deputy Field OCD-District II A	Inspector RTESIA
14. I hereby certify that the foregoing is	Electronic Submission	OIL CORPORA	TIÓN, sent to th	e Carlsbad	•	
Name (Printed/Typed) CINDY BUSH			Title SR. REGULATORY TECH			
Signature (Electronic S	Submission)	Date 01/23/2008				
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE	
Approved By AC PTF			JAMES A AMOS TitleSPET Date 02/02			Date 02/02/2
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsba	nd		

Additional data for EC transaction #58225 that would not fit on the form

32. Additional remarks, continued

well

11-13-07 Started reverse circ. @1435 & drilling broke threw after 8' dwon, had salt ring & drill 2 jts down, stop drilling & lay down swivel, & started RBIH tbg to 3025', POH tbg collars w/bit, broke off bit & pick up scraper & bit. RBIH to 3028' to clean csg, POH tbg, collars, bit & lay down 6 drill collars disconnected reverse unit 11-14-07 RU tbg tester, test 94 jts 2-7/8" tbg RIH & 7" lok set RBP 7" csg 1 pkr, test tbg fine no leaks, test to 4000# set RBP@2994', pkr @ 2974, leak, pmp 30 bbls down cgs didn't load. unset pkr & RBP POH set @ 2974 pkr @ 2940' 1 bbl to laod test to 1150# ok. POH 30 jts set pkr @1985' test down tbg.550# ok, set pkr @1282', small leak, POH w/CS-1 pkr RIH w/7" AD-1 pkr, set pkr @1282' test to 550# ok POH 20 jts set prk @ 640' took 8.5 bbls to laod & 15 bbls to press to 300# loss 50# in 5 min dig out surface valve, open valve pmp down cgs 26 bbls didn't load. 11-15-07 Found csg leak from 640 to surface. POH LD Pkr & RBP 11-16-07 Set CIBP @2974', Got approval from BLM to Plug and Abandon 11-19-07 Spotted 25 sx on top of CIBP @2974' perf @1500' & sqz 35 sx under pkr. Perf #710' 11-20-07 RIH w/BP perf sub 2 7/8 tbg to 1536' didn't tag cmt. spotted 35 sx cmt w3% CACL POH w/20 jts WOC 3 hrs. RIH & tagged @ 1463'. LD 1 jt. Pmp 25 sx cmt @ 1438'. POIH LD 23 jts to 708'. SI production csg & opened up surf csg. Pmp 24 bbls mud down tbg. would not cir up surf. Pmp 35 sx cmt w/4% CaCl. POH & strode back 22jts. LD 15 jts WOC 2 hrs RIH w/20 jts & tagged @ 632'. LD 1 jt RU on súrf and pmp 3 bbls and wtr came up around outside of pipe. Pumped 80 sx cmt w/2% CaCL @ 610' Had circ up prod annulus through last part of job 11-21-07 Tagged cmt @ 184' perf @ 60' Pmp cmt from 184' to surf circ up 7" & surf. ND BOP. Cut off wellhead. Well is P&A

Revisions to Operator-Submitted EC Data for Sundry Notice #58225

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

ABD

NMNM71030A

Agreement:

Lease:

SKELLY UNIT

Operator:

FOREST OIL CORPORATION 707 17TH STREET SUITE 3600 DENVER, CO 80202

Ph: 303-812-1554

Admin Contact:

CINDY BUSH

SR. REGULATORY TECH E-Mail: cabush@forestoil.com

Ph: 303-812-1554 Fx: 303-864-6105

Tech Contact:

CINDY BUSH SR. REGULATORY TECH E-Mail: cabush@forestoil.com

Ph: 303-812-1554 Fx: 303-864-6105

Location

State: County: NM **EDDY**

Field/Pool:

GRAYBURG JACKSON 7-RIVERS

Well/Facility:

SKELLY UNIT 74

Sec 21 T17S R31E 530FSL 330FWL

ABD SR

NMNM98122

NMNM71030A

FOREST OIL CORPORATION 707 17TH STREET SUITE 3600 DENVER, CO 80202

Ph: 303.812.1655 Fx: 303.812.1590

CINDY BUSH

SR. REGULATORY TECH E-Mail: cabush@forestoil.com

Ph: 303-812-1554 Fx: 303-864-6105

CINDY BUSH

SR. REGULATORY TECH E-Mail: cabush@forestoil.com

Ph: 303-812-1554 Fx: 303-864-6105

NM **EDDY**

GRAYBURG

SKELLY UNIT 74

Sec 21 T17S R31E SWSW 530FSL 330FWL