

Report Date: December 14, 2007
3328

Work Order: 7121027
Fairway-Midnight Matador A #3

Page Number: 1 of 2
Eddy County, NM

Summary Report

Gary Miller
Highlander Environmental Services
1910 N. Big Spring Street
Midland, TX, 79705

Report Date: December 14, 2007

Work Order: 7121027



30-015-35697

Project Location: Eddy County, NM
Project Name: Fairway-Midnight Matador A #3
Project Number: 3328

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
144990	NE 2'	soil	2007-12-04	00:00	2007-12-10
144991	NW 2'	soil	2007-12-04	00:00	2007-12-10
144992	SE 2'	soil	2007-12-04	00:00	2007-12-10
144993	SW 2'	soil	2007-12-04	00:00	2007-12-10
144994	Center 2'	soil	2007-12-04	00:00	2007-12-10

Sample: 144990 - NE 2'

Param	Flag	Result	Units	RL
Chloride		916	mg/Kg	2.00

Sample: 144991 - NW 2'

Param	Flag	Result	Units	RL
Chloride		382	mg/Kg	2.00

Sample: 144992 - SE 2'

Param	Flag	Result	Units	RL
Chloride		836	mg/Kg	2.00

Sample: 144993 - SW 2'

Param	Flag	Result	Units	RL
Chloride		548	mg/Kg	2.00

Sample: 144994 - Center 2'

TraceAnalysis, Inc. • 6701 Aberdeen Ave., Suite 9 • Lubbock, TX 79424-1515 • (806) 794-1296

This is only a summary. Please, refer to the complete report package for quality control data.

Accepted for record

NMOC

FEB 26 2008

Delivered to Rock - Cap w/ 20 ml's back fil

Report Date: December 14, 2007
3328

Work Order: 7121027
Fairway-Midnight Matador A #3

Page Number: 2 of 2
Eddy County, NM

Param	Flag	Result	Units	RL
Chloride		812	mg/Kg	2.00