

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Diane Kuykendall
Address: 550 W. Texas Ave., Suite 1300, Midland, Tx 79701	Telephone No. (432) 683-7443
Facility Name: White Star Federal #5 30015-30356	Facility Type: Gas Well - Tank Battery

Surface Owner	Mineral Owner	Lease No. NMLC-069033
---------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter G	Section 29	Township 17S	Range 29E	Feet from the 1650'	North/South Line North	Feet from the 2220'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
NATURE OF RELEASE



Type of Release Oil and water	Volume of Release 3BO & 7BW	Volume Recovered 0 bbls
Source of Release Flow line	Date and Hour of Occurrence Not known	Date and Hour of Discovery 8-9-07 at 8:00 AM NM Time
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD	
By Whom? Keith Conner	Date and Hour 8-9-07 at 10:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
External Corrosion. Replaced with 3" poly line

Describe Area Affected and Cleanup Action Taken.\*  
Highlander Environmental personnel collected soil samples from the spill area. A work plan was submitted to the NMOCD. The work plan was approved by Gerry Guye. The affected soils were excavated and hauled to Controlled Recovery Inc. for proper disposal. A Closure Report was prepared and submitted to the NMOCD for review and approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo	Approved by District Supervisor: 	
Title: Regulatory Analyst	Approval Date: 2/24/08	Expiration Date: N/A
E-mail Address: KCarrillo@conchoresources.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: _____ Phone: (432) 685-4332		

\* Attach Additional Sheets If Necessary

2RP-13