

## APR 08 2008

רי א ידידי

Submit 2 Copies To Appropriate District Office	State of N	lew Mexico	OCD-/	artesia	Form C-103
District I	Energy, Minerals a	nd Natural Ro	esources (	<u> </u>	October 25, 2007
1625 N. French Dr., Hobbs, NM 88240			-	WELL API NO.	/-/ 70
<u>District II</u> 1301 W. Grand Ave, Artesia, NM 88210	OIL CONSERVA	ATION DIV	ISION	5. Indicate Type	005-63678
District III	1220 South	St. Francis I	Or.	STATE	
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe,	NM 87505		6 State Oil & Ga	
1220 S St. Francis Dr., Santa Fe, NM	·				
87505 CUNDRY NOTICE	ES AND REPORTS ON	WELLS		7 Lease Name of	2014 r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA			CK TO A	7. Lease Ivallie of	Olit Agreement Name
DIFFERENT RESERVOIR USE "APPLICA				Stingen	BHG State
PROPOSALS.)  1. Type of Well Oil Well Gas Well Other PA				8 Well Number	BHG State
2. Name of Operator	M3 WCH KI OHICI IA			9. OGRID Numb	er
Yates Petroleum Cor	poration			025575	0.1
3. Address of Operator				10. Pool name or	Wildcat
105 S. 4th Street,	Artesia, NM 8821			Diable SA (1):	Ideat Penrose, Coyale an
4. Well Location					icat ou remose, organic cont
Unit Letter 3 : 660	_feet from the $ oldsymbol{N} $ lin	ne and <b>/980</b> fe	ct from the 👱	line	
· · · · ·	p 105 Range 27E	-			
	11. Elevation (Show whe				
12. Check Appropriate Box to	Indicate Nature of N	otice Report	t or Other D	Nata	
12. Check Appropriate Box to	mulcate mature of m	once, Repon	t of Other D	aia	
NOTICE OF INT	ENTION TO:		SUB	SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REM	IEDIAL WORI	K 📙	ALTERING CASING
	CHANGE PLANS		_	LLING OPNS.	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CAS	SING/CEMENT	L JOB	•
QTHER:			Location is re	eady for OCD inspe	ection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.					
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.					
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR					
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMP					
~					ſ
The location has been leveled as r	nearly as possible to origi	inal ground cor	ntour and has l	been cleared of all j	unk, trash, flow lines and
other production equipment.  Anchors, dead men, tie downs and	d risers have been out off	`at least two fo	et below arou	nd level	
If this is a one-well lease or last re					ted in compliance with
6CD rules and the terms of the Operat					
from lease and well location.					·
All metal bolts and other materials	have been removed. Po	rtable bases ha	ive been remo		
tò be removed.)  All other environmental concerns	have been addressed as	nor OCD miles		ı	APR 9 - 2008
Pipelines and flow lines have been	nave ocen auuresseu as n ahandoned in accordan	ce with 19.15	9 714 B(4)(b)	NMAC AlGerman	hav/Abean.removed from
non-retrieved flow lines and pipelines.	i dominoned in accordan	oc with 15.13.5	2.714.D(4)(0)	MOCI	D-District II ARTESIA
				,	DISTITUTI ARTESIA
When all work has been completed, re					
inspection has to be made to a P&A lo	cation because it does no	ot meet the crite	eria above, a p	enalty may be asses	ssed.
SICMATURE		TILE PRIA	LE	Men A	DATE: 4/1 /03
SIGNATURE Tank	<u> </u>	TILE (RO	ertan Te	110310/4-	DATE DOLLAR
TYPE OR PRINT NAME	HANDS E	-MAIL:	•	F	HONE575-748-1471
For State Use Only				*	1

יו זייויי

יונם חמונים חמו