

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

192463  
13EB0812648306  
13EB0812648097

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company OXY USA WTP LP	Contact Rick Kerby
Address PO Box 1988 102 S Main Carlsbad NM 88220	Telephone No. (O) 505-887-8337 (C) 505-631-4972
Facility Name McKittrick Hill CTB	Facility Type Indian Basin

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

30-015-21010

**LOCATION OF RELEASE**

Unit Letter	Section 14	Township 22 S	Range 24 E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
-------------	------------	---------------	------------	---------------	------------------	---------------	----------------	-------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 132.48	Volume Recovered 0
Source of Release Oil Leak	Date and Hour of Occurrence 10:00 AM	Date and Hour of Discovery 10:30 AM
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Mike Bratcher NMOCD Jim Amos BLM	
By Whom? Rick Kerby	Date and Hour 1:40 PM 5-1-2008	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. \*



Describe Cause of Problem and Remedial Action Taken \*

Hole in the bottom of the tank allowed fluid to leak out on the ground. All fluid contained inside secondary containment.

Describe Area Affected and Cleanup Action Taken. \*

All fluid contained inside berm and work plan will be formulated and forwarded to appropriate government agencies

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rick Kerby	Approved by District Supervisor: 	
Title: HES Tech	Approval Date: 5-5-08	Expiration Date:
E-mail Address: rick.kerby@oxy.com	Conditions of Approval: REMEDIATION	Attached <input checked="" type="checkbox"/>
Date: 4-11-08	Phone: 631-4972	WORK PLAN DUE by 6-9-08

\* Attach Additional Sheets If Necessary

SEB0812648426  
13EB0812648690

2RP-163