

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

ISEB0813354513
NSEB0813354169

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Yates AS #1 Fee	API Number 30-015-10740	Facility Type Battery

Surface Owner Fee	Mineral Owner Federal	Lease No.
----------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter K	Section 25	Township 19N 18S	Range 25E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.72371 Longitude 104.08254

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 B/PW	Volume Recovered 10 B/PW
Source of Release Water Tank	Date and Hour of Occurrence 3/19/2008 PM	Date and Hour of Discovery 3/19/2008 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*



Bottom of 210 bbl water tank broke when being removed (C-144 submitted 12/21/2007; approved 1/8/2008). Vacuum truck called

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 16' X 16'. Produced water picked and contaminates soils excavated and taken to an OCD approved facility. Vertical and horizontal delineation to be conducted, corrective actions will be taken if results are above RRA1's. **Depth to Ground Water: >100' (approximately 100'). Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Robert Asher	Approval Date: 5-12-08	Expiration Date: 6-16-08
Title: Environmental Regulatory Agent	Conditions of Approval: SEE STIPULATIONS	
E-mail Address: boba@ypcnm.com	Attached <input checked="" type="checkbox"/>	
Date: Tuesday, April 29, 2008	Phone: 575-748-4271	

* Attach Additional Sheets If Necessary

SEB0813354755

2RP-167