

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 27 2008

OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

1801
ISEB0816848800
NSEB0816848515

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BEPCO, L.P.	Contact Gary Gerhard
Address P.O. Box 2760 Midland, TX 79705	Telephone No. 432-683-2277
Facility Name Poker Lake Unit #276	Facility Type Wellsite

Surface Owner BLM	Mineral Owner BLM	Lease No NM05912
-------------------	-------------------	------------------

30-015-35137

LOCATION OF RELEASE

Unit Letter G	Section 13	Township T24S 24S	Range R29E	Feet from the 1980	North/South Line FNL	Feet from the 1980	East/West Line FEL	County Eddy
------------------	---------------	-------------------------	---------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude N 32.219389 Longitude W 103.935917

NATURE OF RELEASE

Type of Release Liquid drilling mud	Volume of Release 25 bbls	Volume Recovered None
Source of Release Frac Tanks	Date and Hour of Occurrence 4/16/08 4:30 PM	Date and Hour of Discovery 4/16/08 4:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken *

While transferring drilling mud to frac tanks operator of transfer pump ran frac tanks over Pumps were shut down

Describe Area Affected and Cleanup Action Taken *

Mud ran off location into pasture following shallow gullies out into pasture for approximately 1000' Two backhoes were called out to pick up the impacted dirt and hauled to CRI

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: <i>Gary Gerhard</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Gary Gerhard</i>	Approved by District Supervisor: <i>TCum by SB</i>	
Title: <i>Drilling Engineer</i>	Approval Date: <i>6-16-08</i>	Expiration Date:
E-mail Address: <i>gegerhard@BessPet.Com</i>	Conditions of Approval	Attached <input checked="" type="checkbox"/>
Date: <i>5/23/08</i>	Phone: <i>432-683-2277</i>	<i>2RP-178</i>

* Attach Additional Sheets If Necessary