

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-20615
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Loco Hills A Federal
8. Well Number 7
9. OGRID Number 216852
10. Pool name or Wildcat GB-J-SR-Q-G-SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Water Injection

2. Name of Operator
CBS Operating Corp. JUN 09 2008

3. Address of Operator
P O Box 2236 Midland TX 79702 OCD-ARTESIA

4. Well Location
Unit Letter F 1980 feet from the north line and 1980 feet from the west line
Section 15 Township 17S Range 30E NMPM Eddy County NM

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3697' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: MIT ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

May 28-29, 2008 Had leak-off injection tubing above ground level main valve. Bled well off. Released packer and TOH. Found packer to be bad. Replaced top joint at surface. RIH with new AD-1 plastic coated injection packer. Circulated packer fluid and set packer @ 2547'.

Notified Richard Inge NMOCD for new MIT test. Ran test and hand carried chart to NMOCD representative.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE M.A. Sirgo, III TITLE Engineer DATE 6-6-2008

Type or print name M.A. Sirgo, III E-mail address: mastres@aol.com Telephone No. 432/685-0878

For State Use Only

APPROVED BY: RICHARD INGE TITLE COMPLIANCE OFFICER DATE 6/17/08

Conditions of Approval (if any):

