

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 20 2008
OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

☒ Final Report

Name of Company	St. Mary Land & Exploration Co.	Contact	Tom Morrow
Address	3300 N. A St. Bldg 7, Suite 200, Midland, TX 79705	Telephone No.	432-688-1773
Facility Name	Parkway Delaware Unit #703	Facility Type	Injection Well

Surface Owner	Bureau of Land Management	Mineral Owner	Bureau of Land Management	Lease No.	NM54865
---------------	---------------------------	---------------	---------------------------	-----------	---------

30-015-30027

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	35	19S	29E	2610	South	430	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil / Prod. Wtr.	Volume of Release	4 BO / 40 BW	Volume Recovered	5 bbl Fluid
Source of Release	Inj. Line valve	Date and Hour of Occurrence	5/30/08 8:10 AM	Date and Hour of Discovery	5/30/08 8:10AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos w/ BLM & Mike Bratcher w/NMOCD		
By Whom?	Bill Hearn	Date and Hour	5/30/08 10:01AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

CAUSE: Backed vehicle over live injection line valve, @ ground level, breaking threads off fiberglass injection line.
REMEDIAL ACTION: Closed lateral injection line valve shutting off fluid.

Describe Area Affected and Cleanup Action Taken.*

AFFECTED AREA: 186' X 70'
CLEANUP ACTION: Picked up standing fluid w/vacuum truck. Backhoe dug up soil in spill area 1' deep. Soil samples were taken and chloride leves were okay. Covered spill area with fresh dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Donna Huddleston</i>	OIL CONSERVATION DIVISION	
Printed Name: Donna Huddleston	Approved by District Supervisor: <i>TCum by SB</i>	
Title: Production Tech	Approval Date: <i>7-16-08</i>	Expiration Date: <i>NA</i>
E-mail Address: dhuddleston@stmaryland.com	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/> <i>N/A</i>
Date: 06/18/2008 Phone: 432-688-1789		

* Attach Additional Sheets If Necessary

2RP-180