

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-015-33654

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Barclay Federal

8. Well Number

22

9. OGRID Number

8041

10. Pool name or Wildcat

S. Livingston Ridge Delaware

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Forest Oil Corporation

3. Address of Operator

707 17th Street, Suite 3600, Denver, Colorado

4. Well Location

Unit Letter: F feet from the 2000 line and North feet and 2180 from the West lineSection 12 Township 23S Range 31E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3481 GR

Pit or Below-grade Tank Application ☐ or Closure ☐Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐OTHER: ☒ Rod Repair

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-4-08 - move rig to location, RU PU POH rods to rod part @ shear tool, SION

6-5-08 - open well pick up fish tool RBIH & caught fish, unset pmp POH, LD K-bars & pmp. S.I. got to windy.

6-6-08 - RBIH pmp & rods, hang well load tbg, 500 #, leak 50 # in one min, pres twice, did the same, must have small collars leak, POH rods & tbg, S.I.

6-9-08 - LD 56 - 1.2 F G rods, wind blew off rods from rod basket, RU tbg tester, test tbg BIH found collar leak, replace collar, RBIH pmp & rods, wait on rods to replace SION

6-10-08 - Pick up rods & replace 22 - 1.2 FG rods, hang well, load tbg w/ 27 bbls wtr pres 500# hold good, RD hot oiler, RD PU, left unit running M.O.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

TITLE Sr. Regulatory Tech

DATE 7-11-08

Type or print name

Cindy Bush

E-mail address: cabush@forestoil.com

Telephone No. 303-812-1554

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

Accepted for record - NMOCD