

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|---|---------------|----------------|
| Name of Company | Americo Energy Resources, LLC | Contact | Oscar Nosrati |
| Address | 7575 San Felipe, Ste 200, Houston, TX 77063 | Telephone No. | 713-984-9700 |
| Facility Name | East Shugart Unit Well #15 3001505687 | Facility Type | Injection Well |

| | | | | | |
|---------------|-----|---------------|-----|-----------|--|
| Surface Owner | BLM | Mineral Owner | BLM | Lease No. | |
|---------------|-----|---------------|-----|-----------|--|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| F | 34 | 18S | 31E | 2,310 | North | 2,310 | West | Eddy |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-----------------|----------------------------|----------|
| Type of Release | Produced water and oil | Volume of Release | 150 bbls | Volume Recovered | 130 bbls |
| Source of Release | Blown relief valve | Date and Hour of Occurrence | 6/24/2007 | Date and Hour of Discovery | 6/24/07 |
| Was Immediate Notice Given? | X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Gerry Guye | | |
| By Whom? | Don Gray | Date and Hour | 6/25/07 1:20 pm | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes X No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Injection well supply line ruptured, Replaced line.

Describe Area Affected and Cleanup Action Taken.*

All work has been performed according to the approved Workplan dated February 8, 2008

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|------------------------------------|---------------------|---|---------------------------------------|
| Signature: | | OIL CONSERVATION DIVISION | |
| Printed Name: Jerri Lee | | Approved by District Supervisor: T. Gambay SB | |
| Title: Consultant | | Approval Date: 8-8-8 | Expiration Date: N/A |
| E-mail Address: office@sesi-nm.com | | Conditions of Approval: N/A | Attached <input type="checkbox"/> N/A |
| Date: July 22, 2008 | Phone: 575-397-0510 | | |

* Attach Additional Sheets If Necessary

2RP-146