<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

					OPERATOR			☐ Ini	tial Report	X Final Repo			
Name of Co	ompany A	Americo Ene	urces, LLC		Contact Osc	ar Nosrati							
				n, TX 77063			No. 713-984-970						
Facility Na	me East S	hugart Unit	Well #75	30-015-28	204	Facility Typ	e Injection Wel	1			·········		
Surface Ow	ner BLM		Mineral O	wner l	BLM Lease No.				No.				
				LOCA	TIO	N OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	Fast/V	Vest Line	County			
A	35	188	31E	2,560	South		1,350	West	, est Bille	Eddy			
				-				_					
			La	titude		Longitud	le			,			
				NAT	URE	OF RELI	EASE						
Type of Rele	ase Produc	ed water with	slight oil				Release 350 bbls	s. [Volume F	Recovered 200	0 bbls		
Source of Release						Date and Hour of Occurrence Date and Hour of Discovery							
Blown 'Y' st			12/14/2007 2:00 am 12/14/2007 12 noon										
Was Immediate Notice Given? X Yes □ No □ Not Required						If YES, To Whom? Mike Bratcher							
By Whom? Larry Wood						Date and Hour 12/14/2007 3:00 pm							
Was a Water				If YES, Volume Impacting the Watercourse.									
			Yes X	No									
If a Watercou	ırse was Im	pacted, Descri	ibe Fully.	k		.1					·		
	•	•	Ţ				4						
Describe Cau	se of Proble	em and Remed	dial Action	n Taken.*		· · · · · · · · · · · · · · · · · · ·							
The drain/ble	ed value an	d its nipple blo	ew off the	injection line 'Y'	straine	r. The valve a	and nipple have be	een repla	iced.				
Describe Area	a Affected a	ind Cleanup A	ction Tak	en.*					•		4		
		(5) 1 400)	oo .										
An approximate and tilled.	ate area of 7	'5' by 400' wa	as affected	by the release. A	vacuui	m truck was b	rought onsite to re	emove re	ecoverable	liquids. Soil	will be cleaned		
and tilled.													
I hereby certif	fy that the in	nformation giv	ven above	is true and comple	ete to th	e best of my l	knowledge and un	derstand	that pursu	uant to NMOC	D rules and		
regulations all	l operators a	are required to	report an	d/or file certain re	lease no	otifications an	d perform correct	ive actio	ns for rele	ases which ma	ay endanger		
public health	or the envir	onment. The	acceptanc	e of a C-141 repor	t by the	NMOCD ma	rked as "Final Re	port" do	es not relie	eve the operator	or of liability		
should their o	perations ha	ive failed to a	dequately	investigate and re	nediate	e contamination	on that pose a three	at to gro	und water,	surface water	, human health		
federal, state,	or local lass	untion, NMO	CD accept	tance of a C-141 re	eport do	oes not relieve	tne operator of re	esponsib	nity for co	mphance with	any otner		
rederal, state,	or local law	a and/or regul	ations.				OIL CONS	EDW/	TION	DIVISION			
							OIL CONS	LIK V A	MULL	OT A IOION			
Signature:				· · · · · · · · · · · · · · · · · · ·									
Printed Name: Jerri Lee							Approved by District Supervisor: The District Supervisor:						
			· · · · · · · · · · · · · · · · · · ·		-				<u> </u>	- t			
E-mail Addres	s: office@s	esi-nm.com			(Conditions of A				Attached [_ ، , -		
Date: Augus	st 6, 2008		Phe	one: 575-397-0510	,		NIX	+		/ Kudeneu _	NA		
Attach Additi		s If Necessa								300 1	17		
			-						(JRP-1	ጚ /		