

District I
1625 N French Dr. Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr. Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 505-748-1471	
Facility Name Flora AKF State #1	API Number 30-015-26973	Facility Type Battery
Surface Owner State		Mineral Owner State
Lease No. VO-2597		

AUG 13 2008

OCD-ARTESIA

LOCATION OF RELEASE



Unit Letter N	Section 2	Township 22S	Range 31E	Feet from the 660	North/South Line South	Feet from the 2310	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.41495 Longitude 103.74911

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 4 B/O & 15 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Steel Flow Line	Date and Hour of Occurrence 6/20/2008, AM	Date and Hour of Discovery 6/20/2008, AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully * N/A		
Describe Cause of Problem and Remedial Action Taken * Steel flow line on the west side of the battery developed a leak. Isolated line, shut down well(s), called vacuum truck, backhoe crew and crew to repaired line.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 35' X 15' No oil or produced water to recover. Vertical and horizontal delineation will be made and analysis ran for TPH/BTEX and chlorides (for reference purposes) If initial analytical results for TPH & BTEX are over RRAL's a work plan will be submitted. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. Depth to Ground Water: >100' (approx. 125'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on analytical results, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Robert Asher	Approval Date: 8/13/08	Expiration Date: N/A
Title: Environmental Regulatory Agent	Conditions of Approval: N/A	
E-mail Address: boba@ypcnm.com	Attached <input type="checkbox"/> N/A	
Date: Tuesday, August 12, 2008	Phone: 505-748-1471	

* Attach Additional Sheets If Necessary