

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 23 2008

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name of Company Read & Stevens, Inc	Contact Will Palmer
Address PO Box 1719, Lovington, NM 88260	Telephone No. (575) 396-5391
Facility Name Irene Brainard Com tank battery	Facility Type tank battery

Surface Owner Thomas & Wanda Wilson	Mineral Owner State of New Mexico	Lease No. Fee
-------------------------------------	-----------------------------------	---------------

30-015-2001B

LOCATION OF RELEASE

Unit Letter	Section 20	Township 18S	Range 26E	Feet from the SW/4/NW/4	North/South Line	Feet from the	East/West Line	County Eddy
-------------	------------	--------------	-----------	-------------------------	------------------	---------------	----------------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release produced oil	Volume of Release ~140 bbls	Volume Recovered 10 bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Tank battery circulating line broken and valve opened by livestock	Between 08.18.08 & 08.19.08	08.19.08 0800 hours
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Mike Bratcher, OCD	
By Whom? Mr. Will Palmer	Date and Hour 08.19.08 0815 hours	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Locking valves installed, fencing reconstructed, and 20 mil liner installed inside tank battery along with burms.

Describe Area Affected and Cleanup Action Taken.*

Affected soil removed and taken to approved land farm. Topsoil from landowner installed and area contoured to the lay of the land. Earthen burms constructed and 20 mil liner installed inside tank battery and over burms.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: William V. Palmer	Approved by District Supervisor: 	
Title: Superintendent	Approval Date: 9-24-08	Expiration Date: N/A
E-mail Address:	Conditions of Approval: N/A	Attached <input type="checkbox"/> N/A
Date: September 21, 2008 Phone: 505.396.5391	2RP-218	

Attach Additional Sheets If Necessary

cc: WEN File