Form 3160-5 (August 1999)

Approved by

Conditions of approval, if any:

UNITED STATES DEPARTMENT OF THE INTERIOR


(FEE)
() () () () ()

FORM APROVED OMB NO. 1004-0135

(, lagaot 1000)	BUREA	J OF LAND MANAGEMENT		OCD-Y	EXPIRES:	NOVEMBER 30, 2000		
	SUNDRY NOT	ICES AND REPORTS ON W	ELLS	-	5. Leas \$ gal No.			
		n for proposals to drill or to re e Form 3160-3 (APD) tor suct			N 6. If Indian, Allottee	MNM-66425 or Tribe Name		
	SI	JBMIT IN TRIPLICATE]			
			MOV O a		7. Unit or CA Agree	ment Name and No.		
1a. Type of Well	☑ Oil Well ☐ Ga	s Well Uther	NOV 26	2008	8 Well Name and N	0.		
2. Name of Operat	or		OCD-AR	TEOL	Laguna S	alado 22 Federal 5H		
•	ENERGY PRODUC	VICSIA	9. API Well No.					
Address and Te	•				30-015-36738			
	th Broadway, Oklah	9	10. Field and Pool, or Exploratory					
	(Report location clear NL & 1855 FWL	5	Haroun Ranch; Delaware 12. County or Parish 13. State					
BHL: 330 FS	L & 1980 FWL		多らー <i>こり</i> 点 2310 FSL & 1900 FWL	•	Eddy	NM		
		APPROPRIATE BOX(s) TO II						
TYPE OS 3	SUBMISSION		TYF	E OF ACTION				
☑ Notice of In	tent	Acidize Alter Casing	☐ Deepen☐ Fracture Treat	Production Reclamat	n (Start/Resume)	Water Shut-Off Well Integrity		
☐ Subsequent	Report	Casing Repair	New Construction	Recomple		Other Rig Change	a &	
·	onment Notice	Change Plans	Plug and Abandon		rily Abandon	Variance	, u	
13 Describe Proposed	or Completed Operations (C	Convert to Injection Clearly state all pertinent details, and give	Plug Back	Water Dis		eximate duration thereof. If the	nronosal	
deepen directionally or re	complete horizontally, give s	ubsurface location and measured and tent reports shall be filed within 30 days	true vertical depths of all pertinent m	arkers and zones.	Attach the Bond under which	the work will be performed or	provide	
interval, a Form 3160-4 s	hall be filed once testing has	been completed. Final Abandonment						
determined that the site is	ready for final inspection)			,				
Doyon Energy	Production Co.	npany L. P. respectfully	requests to change f	rom the Mc\	/av Drillia Ria No.	6 to Nahore Pace		
		sts a variance that a co-	· -					
	• ,							
hose will be kept as straight as possible with minimal turns. CO-Flex Hose Manurfacturer: Phoenix Beattie; approximately 22' (7.62 meters) of co-flex line; 3" coupling w/ 4 1 1/16" flanges on each end - 10,000 psi; Quality Control Inspection & Test								
Certificate attached; see configuration schematic. Safety clamps are not required since the ends are flanged.								
						•		
A TT	TACHEDE	OR	A	ለ ረ ቴውጥፑሽ	FOR RECORD)		
SEE ATTACHED FOR CONDITIONS OF APPROVAL								
CONDI	TIONS OF A	APPROVAL						
001				DEC 1	· - 2008			
			0					
		puty Field Inspecto						
(Attachments) NMOCD-District II ARTESIA								
								
14. I hereby certify	that the foregoing is	true and correct Nam	e Judy A. Bar	nett				
Signe	gues Coff	Title	Regulatory Ar		Date	11/17/2008		
(This area is 5	· · · · · · · · · · · · · · · · · · ·				AP	<u> PKUVED</u>	;	
(Inis space for Fed	leral or State Office us	se)				1		

Title

Date



Page: 17/142



PHOENIX RUBBER OUALITY DOCUMENT PROPERTY INDUSTRIAL LTD.

เลงรากระบบ คุณเกมเกมเกรณ์เห็นได้เลยสายเล้าแล้ว เลยสายเลื่อ

H-6728 Szeged, Budapesti út 10. Hungary • H-6701 Szeged P.O.Box: 152 • Phone: (3662) 566-737, Fax: (3662) 566-738 The Court of Csongrad County as Registry Court, Registry Court reg.No.: Cg.06-09-002502

QUALITY CONTROL INSPECTION AND TEST CERTIFICATE							ļ*:	688		
PURCHASER: Phoenix Beattle Co.							₽.0. №: 000573			
PHOENIX ORDER Nº: 3	HOSE	TYPE:	3"	ID	Cho	ke and K	ill Hose			
HOSE SERIAL Nº: 46226			NOMINAL / ACTUAL LENGTH:				7,62 m			
W.P. 68,96 MPa 10	000 psi	T.P.	103,4	MPa	1500	iaq O	Duration:	60	min.	
Pressure test with water at ambient temperature See attachment. (1 page)										
→ 10 mm = 16 MPa								17 W		
			COUP	LINGS	<u></u>					
Туре		Serial	Nº	_ _	· · · · · · · · ·	Quality		Heat	N°	
3" coupling with	77.	4	791		AIS	81 4130		445651	59681	
4 1/16" Flange end		•		Als	AISI 4130		59534	59681		
API Spec 16 C Temperature rate: "B" All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT.										
Date: 29. March, 2006	Inspector			Qualit	y Contro Bach	lt.du lose In	IX KUBE strial Ltd. kpection i cation Do	and	·	


15 60

No.: 684,687,688 Page: 1/1

4114 4 5 5 4 6 5	2	111111111111111111111111111111111111111	PHOTOLIX ROLBER
EPF TELLET OF	20:00		The Respection and
**************************************	11 11 19 56	+++	iawi nelia: http://www.
#07	14- 550 19- 50		
RD+ +21 82 PC	9 39		
#01 +21 91 PC #1 +1948 65	396 396 4		
RD7 121 190 PC	9:20		
	40 3 10 40 3 10 3 10 3 10 3 10 3 10 3 10 3 10 3 1	60 1 80	1100
12 1855	. 1 1 1 9 6 6		
45226,4	5223 45 225 12:4		
#6220.4	52231, 4 <u>55251, 4</u> 2+3		
10			

]

M41 Choke hose



. . -

. --

Laguna Salado 22 Federal 5H 30-015-36738 Devon Energy Production Company, LP November 19, 2008 Conditions of Approval

1. Variance approved to use flex line from BOP to choke manifold. Check condition of 4-1/16" flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends.

WWI 111908

/ . i