

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action



N5EB0835741498		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Judah Oil, LLC		245872		Contact James B Campanella	
Address P.O. Box 568, Artesia, NM 88211-0568				Telephone No. 575-746-1280	
Facility Name Lucy Pearl State 002				Facility Type Oil Storage	
Surface Owner State		Mineral Owner State		Lease No. E-4205	

30 015 23337								LOCATION OF RELEASE	
Unit Letter G	Section 2	Township 22-S	Range 28-E	Feet from the 1712	North/South Line North	Feet from the 2310	East/West Line East	County Eddy	

Latitude _____ Longitude _____

NATURE OF RELEASE 85

Type of Release Oil	Volume of Release 25 bbls	Volume Recovered 40 bbls
Source of Release Hole in stock tank	Date and Hour of Occurrence 10:00 am	Date and Hour of Discovery 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher w/ NMOCD Artesia Dist.	
By Whom? James B Campanella	Date and Hour 11-14-2008 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Hole in production tank. Called for vacuum truck and transport. Transferred oil from bad tank to good tank. Picked up 40 bbls of oil from ground and took to Oxy T-Bone SWD		
Describe Area Affected and Cleanup Action Taken.* North side of tank batt. 20'x20' ran south of batt down 10" path to low area. Low area is 25'x20'		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: James B Campanella		Approved by District Supervisor: 	
Title: Manager/President		Approval Date: 12-22-08	Expiration Date: 2-22-09
E-mail Address: judahoil@yahoo.com		Conditions of Approval:	
Date: 11-15-2008 Phone: 575-746-1280		Attached <input checked="" type="checkbox"/>	
Attach Additional Sheets If Necessary		Attached work plan approved with strips.	
		2RP - 282	

Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.