

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

File  
Copy

10-015-32668

Release Notification and Corrective Action

10-015-32668  
VAB0334328399. OPERATOR ☐ Initial Report ☒ Final Report

Name of Company	Shackelford Oil Company	Contact	Don Shackelford
Address	P O Box 10665 Midland, TX 79702	Telephone No.	(432) 682-9784
Facility Name	EDDY IK #2 Well	Facility Type	Well

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No.
---------------	---------------------	---------------	---------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	2	20S	29E	1980'	North	2310'	West	Eddy

Latitude 32° 36' 15.39" N Longitude 104° 02' 46.31" W

NATURE OF RELEASE

Type of Release	Oil and Water	Volume of Release	5 b1	Volume Recovered	
Source of Release	Eddy IK #2 Well	Date and Hour of Occurrence	1/30	Date and Hour of Discovery	2:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED

DEC - 8 2003

OCD-ARTESIA



Describe Cause of Problem and Remedial Action Taken.\*

Pinhole in flowline from the Eddy IK #2 to Tank Battery.  
Clamped hole in flowline.

Describe Area Affected and Cleanup Action Taken.\*

Area 20' x 20' 2" Deep  
Applied fertilizer to affected area at rate of 1/2 lb. per square yard and raked into spill area thoroughly.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Don Shackelford		Approved by District Supervisor: 	
Title: Owner	Approval Date: 12-10-03	Expiration Date:	
E-mail Address: dg-shack@swbell.net	Conditions of Approval: OK for Release / s.	Attached <input type="checkbox"/>	
Date: 12/5/2003	Phone: (432) 682-9784		

\* Attach Additional Sheets If Necessary