

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-24485

Release Notification and Corrective Action

MLB0915353481

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	John W. Gates
Address	3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No.	505.391.3158
Facility Name	Illinois Camp Well No 1	Facility Type	Oil and Gas
Surface Owner	State Of New Mexico	Mineral Owner	State Of New Mexico
		Lease No	30015244485

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K E	5	18S	<del>38E</del> 28E	1980	North	990	West	Eddy

Latitude 32 46 684 Longitude 104 12 161

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Crude Oil & Produced Water	90bbl (51oil, 39water)	(0oil, 0water)
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
3X4" Swedge on east side of tank	2/26/09 NA	2/26/09 1024
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Geoffrey Leking NMOCD	
By Whom? John Gates	Date and Hour 2/26/09 1430	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

3X4 inch swedge on east side of north tank failed due to internal/external corrosion. There were no fluids recovered. The tank was isolated, drained and removed from service.

Describe Area Affected and Cleanup Action Taken.\*

15' X 36' area inside caliche dike with no cattle present. There were no fluids recovered. Spill site will be delineated and remediated in accordance with NMOCD guidelines

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by District Supervisor 	
Title: HSER Lead	Approval Date: JUN 09 2009	Expiration Date:
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: Remediation per NMOCD Rules & Guidelines	Attached <input checked="" type="checkbox"/>
Date: 02/26/2009	Phone: 505.391.3158	

- Attach Additional Sheets If Necessary

MLB0915354261

2RP-314