District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505


## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 JUN -8 2009


Form C-141 Revised October 10, 2003


Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form


30-015-	৻ৢঽঽৢ৾৽	co	Rele	ease Notific	catio	n and Co	rrective A	ction			
nMLB091	14231	<i>₹ŲU</i>				OPERA'	ГOR		Initial Report	X	Final Repor
Name of Co			10:	\		Contact	Belton 1	Matheus			
Address	Soy 19	38		NV eller		Telephone l	No. 677.	2313			. <del></del>
Facility Na	ne Giss	les B	431			Facility Typ	e Pumpin	g well			
Surface Ow	ner F	A		Mineral C	)wner			Lea	ase No. <b>07</b> 4	1939	
API · 3				LOCA	TIO	N OF REI	LEASE				
Unit Letter	Jnit Letter   Section   Township		Range Feet from the		North	/South Line	Feet from the	East/West L	ine County	4	
4	14	17	30	1650	F.	5L	990	FWL	21	24	
Type of Relea		14 water	<b>.</b>	titude <u>32 49</u> NAT		OF RELI	EASE	<b>s</b> Volu	me Recovered and Hour of Di	O .	
Source of Rel Was Immedia	ease <b>57</b> te Notice G	iven?		No 💢 Not Re	quired	If YES, To	Whom? 5/1		and Hour of Di	scovery	
By Whom?						Date and Hour  If YES, Volume Impacting the Watercourse.					
Was a Watero	ourse Reac	hed?	Yes 🔀	No		II YES, Vo	ume impacting ti	ne watercours	se.		
If a Watercou	Y	Danami	La Enlly *			<u> </u>					
Describe Area	posk	y at on	t fu	om leak					<u> </u>		
				and he			ovald bel 6 CR	~ Samul	-		
regulations all public health of should their of	operators a or the enviro perations ha nent. In ad	re required to onment. The a ve failed to ac dition, NMO	report and acceptance lequately i CD accept	is true and comple d/or file certain re- e of a C-141 repor investigate and re- ance of a C-141 re-	lease no t by the mediate	tifications and NMOCD ma contaminatio	d perform correct: ked as "Final Renthat pose a threathe operator of renthat pose a threathe operator of renthat pose."	ive actions for port" does not at to ground we sponsibility f	releases which relieve the ope vater, surface water compliance v	may end rator of later, hum with any	danger liability nan health
Signature:	200	كسا					OIL CONS	ERVATIO	ON DIVISIO	<u>DN</u>	
Printed Name:	Eld	نف س	Sear		A	approved by E	diamed Bieryson	11/4 DKM	muse_		
Title: Age.	<del></del>		~ <del></del>	· · · · · · · · · · · · · · · · · · ·	A	pproval Date	IUN 1 1 200	9 Expirati	on Date:		
E-mail Addres	s: 500	4 24 6	) / eac		c	Conditions of A	Approval:		Attached		
Date: La 3 (	onal Sheets	s If Necessar		2.2636		***************************************	······································	····			



Bafore Cleanup











ANALYTICAL RESULTS FOR EDDIE SEAY CONSULTING ATTN: EDDIE SEAY 601 W. ILLINOIS HOBBS, NM 88242 FAX TO: (575) 392-6949

Receiving Date. 05/29/09

Reporting Date: 08/03/09

Project Owner: BURNETT
Project Name: GISSLER B #31

Project Location: LOCO HILLS, NM

Sampling Date: 05/28/09

Sample Type: SOIL

Sample Condition: INTACT @ 13°C

Sample Received By. ML Analyzed By: AB/HM

LAB NUMBER SAMPLE ID	GRO (C <sub>e</sub> -C <sub>10</sub> ) (mg/kg) 06/03/09	DRO (>C <sub>10</sub> -C <sub>28</sub> ) (mg/kg)	CI (mg/kg) 05/29/09
ANALYSIS DATE H17506-1 GB-31-1	<50.0	06/03/09 420	<16
Quality Control	507	488	490
True Value QC	500	500	500
% Recovery	101	978	98.0
Relative Percent Difference	1.7	<0.1	2.0

METHODS: TPH GRO & DRO: EPA SVV-846 8015 M; Std. Methods 4500-CITB \*Analysis performed on a 1:4 w:v aqueous extract. Reported on wet weight.

Lab Director

06/03/09 Date