

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-10822

Release Notification and Corrective Action

15EB 0829130697

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 685-4332
Facility Name	GJ COOP Unit #47	Facility Type	Injection well

Surface Owner	Mineral Owner	Lease No.	30-015-10822
---------------	---------------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	21	17S	29E	660	North	1980	West	Eddy

Latitude N 32°49.527 Longitude W 104°04.917

NATURE OF RELEASE

Type of Release Oil and /or produced water	Volume of Release 20 bbls	Volume Recovered 8 bbls
Source of Release flowline	Date and Hour of Occurrence Unknown 9/30/08 5:30 AM	Date and Hour of Discovery 9/30/08 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom?	Date and Hour 10/1/08 9:10 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Contractor truck turned too sharp and ran over steel swing in flowline. Replaced the damage piece of flowline.

Describe Area Affected and Cleanup Action Taken.*

Leak was contained to the side of the lease road and middle of lease road. All liquids were pick up and sand was spread on affected area on the lease road. Tetra Tech collected samples and defined extents. Impacted soil was removed above RRAL and hauled to proper disposal. Tetra Tech prepared and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by  Signed By Supervisor	
Title: Project Manager	Approval Date: JUL 23 2009	Expiration Date: N/A
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 7-13-09	Phone: (432) 682-4559	

* Attach Additional Sheets If Necessary

2RP-253