

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-34645

Release Notification and Corrective Action

15EB 0902751176

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-682-4559
Facility Name -	Skelly #942 Bty	Facility Type	PRODUCTION

Surface Owner	BLM	Mineral Owner		Lease No.	API# 30-015-34645
---------------	-----	---------------	--	-----------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	17S	31E	1210	North	2195	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Water/Oil	Volume of Release	50bbls	Volume Recovered	none
Source of Release	Test Vessel	Date and Hour of Occurrence	10/30/08- 6:00am	Date and Hour of Discovery	10/30/08- 7:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos w/BLM & Mike Bratcher w/OCD		
By Whom?	Date and Hour 10/30/08, 11:10am				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

2" hose on trailer/portable production tester failed and leaked. Affected area will be dug out and removed.

Describe Area Affected and Cleanup Action Taken.*

Approximately 50' x 100' on Bty location and lease road entering battery location was sprayed when hose failed. The affected area was scraped and the material hauled off. Tetra Tech collected soil samples. Copies are included with this C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Timothy Reed (Agent for COG)	Approved by District Supervisor 		
Title: Senior Project Manager	Approval Date: JUL 23 2009	Expiration Date: N/A	
E-mail Address: timothy.reed@tetratech.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>	
Date: 1/29/09	Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary

2RP-323