

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-24485

Release Notification and Corrective Action

2RP 314

NMLB09153 53481

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Jesse Sosa
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 575-391-3126
Facility Name Illinois Camp Well No 1	Facility Type Oil & Gas

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No. 30-015-24485
-----------------------------------	-----------------------------------	------------------------

LOCATION OF RELEASE

Unit Letter E	Section 5	Township 18S	Range 28E	Feet from the 1980	North/South Line North	Feet from the 990	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32 46 684 Longitude 104 12 161

NATURE OF RELEASE



Type of Release Crude oil & produced water	Volume of Release 90 bbl (51 oil, 39 water)	Volume Recovered (0 oil, 0 water)
Source of Release 3X4" Swedge on east side of tank	Date and Hour of Occurrence 2/26/09 NA	Date and Hour of Discovery 2/26/09 1024
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking NMOCD	
By Whom? John Gates	Date and Hour 2/26/2009 1430	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\*  
#X4" swedge on east side of north tank failed due to internal/external corrosion. There were no fluids recovered. The tank was isolated, drained and removed from service.

Describe Area Affected and Cleanup Action Taken.\*  
Liquids were contained within 35 X 55 ft tank diked area. The release was delineated and remediated in accordance with NMOCD guidelines. See attached document.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jesse Sosa		Approved by District Supervisor 	
Title: HSE Lead		Approval Date: SEP 28 2009	Expiration Date: N/A
E-mail Address: jesse.a.sosa@conocophillips.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: Sept 25, 2009 Phone: 575-391-3126			

\* Attach Additional Sheets If Necessary

2RP-314