

OCT 05 2009

Submit One Copy To Appropriate District Office

State of New Mexico
Energy, Minerals and Natural ResourcesForm C-103
March 18, 2009

District I
1625 N. French Dr., Hobbs, NM 88240

District II
1301 W. Grand Ave., Artesia, NM 88210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. <u>30015 03581</u>
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. <u>8742</u>
7. Lease Name or Unit Agreement Name <u>STATE T</u>
8. Well Number <u>1</u>
9. OGRID Number <u>9259</u>
10. Pool name or Wildcat <u>R- CB Santa 7 Turkey</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

H. Duane Parish LLC

3. Address of Operator

1306 S. 9th Artesia NM 88210

4. Well Location

Unit Letter E: 1650 feet from the Rock line and 990 feet from the West lineSection 12 Township 19S Range 29E NMPM County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐☒ Location is ready for OCD inspection after P&A☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ All other environmental concerns have been addressed as per OCD rules.
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. Funds have been removed from non-retrieved flow lines and pipelines.

DENIED

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE [Signature] TITLE owner DATE 9-18-09

TYPE OR PRINT NAME _____ E-MAIL: _____ PHONE: 575 723 5576

For State Use Only

APPROVED BY: [Signature] TITLE NO Release DATE 10/6/09

Conditions of Approval (if any): Pump Jack on location