

Final Report

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmcb/1002852212 OPERATOR ☐ Initial Report ☒ Final Report

| | |
|--|------------------------------|
| Name of Company - EnerVest Operating LLC 143199 | Contact - Elroy Ardoin |
| Address - 1001 Fannin Street, Suite 800, Houston, TX 77002 | Telephone No. (713) 495 6534 |
| Facility Name - West Loco Hills Unit Tract 1 Well #26 | Facility Type - Pump Jack |
| Surface Owner - State of New Mexico | Mineral Owner |
| API No. 30-015-03233 | |

LOCATION OF RELEASE

| | | | | | | |
|------------------|--------------|-----------------|--------------|-----------------------------|---------------------------------|----------------|
| Unit Letter n | Section 1 | Township 18S | Range 29E | Feet from the South Line | Feet from the East/West Line | County Eddy |
|------------------|--------------|-----------------|--------------|-----------------------------|---------------------------------|----------------|

Latitude 32.77184 Longitude -104.02964

NATURE OF RELEASE

| | | |
|---|---|------------------------------------|
| Type of Release - Produced Water/Saltwater | Volume of Release - estimated 20bbls | Volume Recovered - 0bbls |
| Source of Release - Flow Line | Date and Hour of Occurrence ? | Date and Hour of Discovery 3/24/08 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* EnerVest Operating currently operates this lease. The original c141 was voluntarily submitted by Texas ReExploration Operating. A flow line leak resulted in an approximate 20bbl saltwater spill. No action was taken by Texas ReExploration other than to repair the flow line where the leak originated. EnerVest Operating contracted Baseline Solutions to conduct an environmental remediation using the "dig and haul" method. | | |
| Describe Area Affected and Cleanup Action Taken.* The effected area was 10yds X 50yds. There was little to no vegetation growing within the spill area. The highest level of chlorides sampled was 3320ppm and the highest level of TPH was 245ppm. The remediation method was "dig & haul" operations with lab analysis. Contaminated soil was excavated and delivered to Lea Land Disposal. Upon completing the excavation, soil samples were taken to test for Chlorides and TPH. Lab analysis determined the levels were in compliance with OCD requirements. A sampling investigation and excavation report was submitted to OCD for approval to backfill. The site was backfilled with soil from Lea Land Disposal. The site was re-seeded. Vegetation has returned to the spill area. A closing report was submitted to NMOCDA Artesia office. The remediation project is considered successfully completed. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDA rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDA marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDA acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <i>Elroy L. Ardoin</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Elroy L. Ardoin | Approved by <i>M. L. Brumby</i> | |
| Title: HSE Coordinator | Approval Date: FEB 02 2010 | Expiration Date: |
| E-mail Address: eardoin@enervest.net | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 1/20/2010 Phone: (713) 495 6534 | | |

* Attach Additional Sheets If Necessary

nmcb/1003340232

2RP-382