

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

FEB - 5 2010

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

☒ Final Report

Name of Company	Lime Rock Resources	Contact	Michael Barrett
Address	1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No.	575-623-8424 505-353-2644
Facility Name	Staley State A #4	Facility Type	Oil Well

Surface Owner	Pulitzer Broadcasting	Mineral Owner	State of New Mexico	Lease No.	30-015-36252
---------------	-----------------------	---------------	---------------------	-----------	--------------

30-015-36252

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	30	17S	28E	990'	FSL	1980'	FWL	Eddy

Latitude 32° 48 08.34" North

Longitude 104° 12 58.91" West

NATURE OF RELEASE

Type of Release	Produced Water and crude oil	Volume of Release	20 Bbls Oil, 75 Bbls Water	Volume Recovered	none
Source of Release	Poly Line Failed	Date and Hour of Occurrence	11/7/09 @ 0600	Date and Hour of Discovery	11/7/09 @ 0600
Was Immediate Notice Given?	X Yes No Not Required	If YES, To Whom?	Sherry Bonham		
By Whom?	Michael Barrett	Date and Hour	11/9/09 @1000		
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes No	If YES, Volume Impacting the Watercourse.	50 Bbls of total fluid		

If a Watercourse was Impacted, Describe Fully.\*

Runoff from leak to low lying area

Describe Cause of Problem and Remedial Action Taken:

Frac sand plugged 3" poly line causing it to fail.



Shut in wells, isolated line, cleared plug and repaired.

Describe Area Affected and Cleanup Action Taken.

Release site was remediated to applicable NMOCD standards, please see Basin Consulting *Remediation Summary and Site Closure Request*.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		Approved by District Supervisor			
Printed Name:	Michael Barrett	Signed by 			
Title:	Production Supervisor	Approval Date:	2-5-10	Expiration Date:	N/A
E-mail Address:	mbarrett@limerockresources.com	Conditions of Approval:		N/A	
Date:	11/10/09	Phone:	505-353-2644	LPP-364	