FEB 1 6 2010

NMOCD ARTESIA Submit One Copy To Appropriate District State of New Mexico Form C-103 Office March 18, 2009 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-00668 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. FEE STATE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM E1059 87505 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Red Lake II Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number 10 1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other 2. Name of Operator 9. OGRID Number Fairway Resources Operating, LLC 241598 10. Pool name or Wildcat 3. Address of Operator 538 Silicon Dr., Suite 101, Southlake, TX 76092 Red Lake, QN, GB, SA 4. Well Location Unit Letter G: 1650 feet from the North line and 2310 feet from the East line Township 17S Range 27C NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3629' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON | **REMEDIAL WORK** ALTERING CASING □ TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.□ P AND A  $\boxtimes$ PULL OR ALTER CASING MULTIPLE COMPL  $\Box$ CASING/CEMENT JOB П OTHER: □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. Mark The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. ☐ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. A producing well operated by someone else shares the pad location for this well. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. A producing well operated by someone else shares the pad location for this well. TITLE Engineering Tech DATE 2/10/2010 TYPE OR PRINT NAME Star Hasse E-MAIL: shasse@fairwayresources.com PHONE: 817-416-1946 x223 For State Use Only o Kelsese

APPROVED BY:

Conditions of Approval (if any)