

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

N3EB1009047982

Release Notification and Corrective Action

ISEB1009048261 SEA1009048337 PSEB1009048787

OPERATOR

☐ Initial Report

☒ Final Report

Name of Company	COG Operating LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 685-4332
Facility Name	Skelly Unit 606	Facility Type	Tank Battery

Surface Owner	Mineral Owner	Lease No.	30-015-36765
---------------	---------------	-----------	--------------

30-01536765

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	21	17S	31E	2110	South	2310	East	Eddy

Latitude N 32.818480° Longitude W 103.873063°

NATURE OF RELEASE

Type of Release: <b>Produced water</b>	Volume of Release <b>20 bbls</b>	Volume Recovered <b>15 bbls</b>
Source of Release <b>Flowline leak</b>	Date and Hour of Occurrence <b>10/10/09 AM</b>	Date and Hour of Discovery <b>10/10/09 AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Flowline leaked. COG repaired flowline. Spill remained on pad and did not go into pasture.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech inspected site and collected samples to define spills extent. Soil with elevated chlorides concentration were removed and hauled away to Controlled Recovery, Inc., Hobbs, NM. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez		Approved by District Supervisor: 	
Title: Project Manager		Approval Date: 3/31/10	Expiration Date: N/A
E-mail Address: ike.tavarez@tetratech.com		Conditions of Approval: N/A	Attached <input checked="" type="checkbox"/> N/A
Date: Phone: (432) 682-4559			

\* Attach Additional Sheets If Necessary

2RP-394

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

\*\*\*Amended Report

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC 229137	Contact Kanicia Carrillo
Address 550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - Skelly Unit 606	Facility Type- Battery

Surface Owner State	Mineral Owner	Lease No. 30-015-36765
---------------------	---------------	------------------------

30 015 36765

LOCATION OF RELEASE

Unit Letter J	Section 21	Township 17S	Range 31E	Feet from the 2110	North/South Line South	Feet from the 2310	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.818480 Longitude 103.873063

NATURE OF RELEASE

Type of Release-Produced Water	Volume of Release-20bbls	Volume Recovered- 15bbls
Source of Release- Flowline leak	Date and Hour of Occurrence- 10/10/09 am	Date and Hour of Discovery 10/10/09 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Flowline leak. Repaired leak. Spill remained on pad and did not go into pasture.

Describe Area Affected and Cleanup Action Taken.\*

Vacuumed up all fluid. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Kanicia Carrillo

Title: Regulatory Analyst

E-mail Address: kcarrillo@conchoresources.com

Date: 10/21/09

Phone: 432-685-4332

Approved by District Supervisor: 

Approval Date: 3/31/10

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-394