


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-00802

**Release Notification and Corrective Action**

nmB1016047459

**OPERATOR**

☐ Initial Report

☐ Final Report

Name of Company <b>Devon Energy</b>	Contact <b>Robert Bell, Foreman</b>
Address <b>6488 Seven Rivers Hwy - P.O. Box 250</b>	Telephone No. <b>575-748-7448</b>
Facility Name <b>WRL State #1</b>	Facility Type

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter <b>M</b>	Section <b>6</b>	Township <b>18s</b>	Range <b>27E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	---------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>50 bbls</b>	Volume Recovered <b>50 bbls</b>
Source of Release <b>Water transfer line ruptured</b>	Date and Hour of Occurrence <b>05/19/10 - 2:45 pm</b>	Date and Hour of Discovery <b>05/19/10 - 2:45 pm</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Todd Suter</b>	
By Whom? <b>Tommy Polly, Assistant Foreman</b>	Date and Hour <b>05/19/10 - 4:45</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <b>4" water transfer line ruptured &amp; released 50 BBLS of produced water.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>Approximately 50 BBLS of produced water ran down draw. Contacted BLM rep &amp; was instructed to flush draw with 100 BBLS of fresh water. We flushed draw with 390 BBLS of fresh water. Total water recovered was 350 BBLS</b>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Mykol Horner</b>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Mykol Horner</b>	Approved by <u>Signed By <b>Mike Benavidez</b></u> District Supervisor:	
Title: <b>Field Tech 1</b>	Approval Date: <b>JUN 09 2010</b>	Expiration Date:
E-mail Address: <b>mykol.horner@dvn.com</b>	Conditions of Approval: REMEDATION per OCD Rules and Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input checked="" type="checkbox"/>
Date: <b>05/24/10</b> Phone: <b>575-748-0160</b>	PROPOSAL BY: <u><b>June 30, 2010</b></u>	

\* Attach Additional Sheets If Necessary

nmB1016047459

2RP-418