


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-015-29291

NMLB1016045870

**OPERATOR**

☐ Initial Report

☐ Final Report

Name of Company	Devon Energy	6137	Contact	Jerry Matthews, Foreman
Address	6488 Seven Rivers Hwy - P.O. Box 250			Telephone No. 575-748-5234
Facility Name	Ore Ida 14 Federal #12			Facility Type

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	24S	29E	1880	FSL	2480	FWL	Eddy

Latitude - N 32.21516 \* Longitude - 103.94927

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>15 bbls</b>	Volume Recovered <b>0</b>
Source of Release <b>Flowline</b>	Date and Hour of Occurrence <b>05/27/10 - 11:30 am</b>	Date and Hour of Discovery <b>05-27-10 - 11:30 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Jim Amos</b>	
By Whom? <b>Eric Bell, Lease Operator</b>	Date and Hour <b>05-27-10 - 3:50 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

**On arrival at the Ore Ida 14 #12 the Lease Operator observed some guys doing some dirt work near our poly line; also observed standing water. Went to investigate where it was coming from and an employee from B&H informed Lease Operator that they discovered the leak and went into town to get a clamp and they tried clamping the line. Called and had gang come out and fix line**

Describe Area Affected and Cleanup Action Taken.\*

**Took clamp off and repaired line and will teal, rake, and fertilize affective area on location.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Mykol Horner</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Mykol Horner</b>	Approved by District Supervisor: <u>[Signature]</u>	
Title: <b>Field Tech 1</b>	Approval Date: <b>JUN 09 2010</b>	Expiration Date: <b></b>
E-mail Address: <b>mykol.horner@dv.com</b>	Conditions of Approval: <b>REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: June 30, 2010</b>	Attached <input type="checkbox"/>
Date: <b></b> Phone: <b>575-748-0160</b>		

\* Attach Additional Sheets If Necessary

NMLB1016046546

2RP-417