Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No 1004-0137

Expires July 31, 2010

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals abandoned well. Use Form 3160-3 (A	APD) for such proposals.	DD ARTE Signal an, Allotte	ee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2.		7 If Unit or CA/A	7 If Unit or CA/Agreement, Name and/or No	
1 Type of Well  X Oil Well Gas Well Other		8 Well Name an	d No	
2 Name of Operator		Sand Tank	Sand Tank APS Fed Com #2H	
Yates Petroleum Corporation		9 API Well No		
3a Address	3b Phone No (include area code)	30-015-371	30-015-37167	
105 S. 4th Str., Artesia, NM 88210	575-748-1471		10 Field and Pool or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M., OR Survey Description			Bone Spring	
Surface - 460'FSL & 380'FEL of Section 12-T18S-R29E (Unit P, SESE)			11 County or Parish, State  Eddy County, New Mexico	
BHL - 660'FSL & 330'FWL of Section 12-T18S-R29E (Unit M, SWSW)  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NO			·	
			THERDAIA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
Notice of Intent Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Casing Repair	New Construction	Recomplete	X Other Spud, surface	
Subsequent Report	<u></u>			
Change Plans		Temporarily Abandon	and intermediate	
Final Abandonment Notice Convert to Ir	pection Plug Back	Water Disposal	casing	
testing has been completed. Final Abandonment Notices must be filed to determined that the site is ready for final inspection.  5/21/10 Spudded well and set 40' of 20" cond.  5/25/10 Resumed drilling at 2:45 PM.  5/26/10 TD 14-3/4" hole to 472'. Set 11-3/4" + 2% CaCl (yld 1.35, wt 14.8). Taile did not circulate. Ran temperature si 133'. Picked up to 118'. Ran 1" centat 25'. Ran 1" cement to surface with psi, OK. WOC 32 hrs. Reduced hole to 3276'. Set 8-5/8" 32# + 5#/sx Gilsonite + 0.125#/sx Polyee Lite (yld 1 33, wt 14.8). Cement circulate at 25'. Reduced hole to 7-7/8" and resumed.	ductor, cemented with 11 yds of 42# H-40 ST&C casing at 472 d in with 100 sx Premium Plus survey and showed TOC at 90' nent to surface with 100 sx. Direct to 11" and resumed drilling. 4 J-55 ST&C casing at 3276'. Called to 5% salt (yld 1.85, wt 12 ulated to surface. Tested casing	ement.  '. Cemented with 250 s + 2% CaCl (yld 1.35, with picked up 1" pipe and do not circulated cement ated 12 sx to pit. Tested Cemented with 650 sx P 2.9). Tailed in with 200 semented with	ex Premium Plus t 14.8). Cement tagged cement at Tagged cement d casing to 1200 Premium Plus Lite sx Premium Plus	
14 I hereby certify that the foregoing is true and correct				
Name <i>(Printed/Typed)</i> Tina Huerta ,	I <sub>Title</sub> Regulato	ry Compliance Supervis	sor	
11'		, :	- ~	
Signature (June) duerta,	Date June 18,	2010	- FOODD	
THIS SPA	ACE FOR FEDERAL OR STATE OFF	AGGEPTED FUR	RECORD	
Approved by  Conditions of approval, if any, are attached Approval of this notice certify that the applicant holds legal or equitable title to those right which would entitle the applicant to conduct operations thereon  Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, male any false fictions or fraudulent statements or representations as to	ghts in the subject lease Office	JUL 9 201 /s/ Dustin Win	l0 ikler	
ary raise, nettied of radiation diagonistic of representations as a	o any matter within its jurisdiction	BUREAU OF LAND MAN CARESBAD FIELD O	CTIOT I	
(Instructions on page 2)		127		