

☐ Initial Report

<u>District I</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
13 01 W. Grand Avenue, Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Road, Aztec, NM 87410
<u>District IV</u>
12 20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

X Final Report

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30.	015-	2452	9
-----	------	------	---

Release Notification and Corrective Action

OPERATOR

1 value of Co	mpany		1 12101 67,			COMMAN FOR COMPANI						
Address PO Box 50682					Telephone No. 432-684-4748							
Facility Nan	ne Feder	al Littlefield	"BO" T	ank Battery		Facility Typ	e Tank Battery	∕- Oil as	ad Produc	ed Water Storage		
Surface Own	ner Fed	lcral		Mineral C	Wher	Fee	leral		Lease No. LC-065928A			
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/W	est Line	County		
A	34	26S	29Ē	~724	N		~660	E		Eddy		
Latitude N 32 0' 12.10" Longitude W -103 57' 59.06"												
NATURE OF RELEASE												
Type of Release Produced Oil						Release ~92.5 Bi	ecovered ~20 Bbis					
Course of Del	oooo Oil C	torage Tent	 			Date and L	Date and House of Occupany			Date and View of Discourse		
Source of Release Oil Storage Tank					Date and h	Date and Hour of Occurrence			Date and Hour of Discovery			
Was Immedia	te Notice G	lven?				If YES, To	Whom? Bureau	of Land	Managome	ent notified GP II Energy that a		
Yes X No Not Required spill had been reported by the New Mexico OCD field inspector at the Federal Littlefield "BO" tank bettery.								D field inspector at the Federal				
							our Check with E					
Was a Watero	ourse Reac			_		If YES, Vo	lume Impacting th	ne Water	COUTSE.			
☐ Yes No												
If a Watercour	se was Imp	acted, Descri	be Fully.*				·					
Describe Cause of Problem and Remedial Action Taken. *Worked over Federal "BO" #6. Well flowed during night and pushed water from the gun barrel into oil storage tank. Equalizer was unable to accommodate flow and oil ran over the storage tank. We are going to install a larger gun barrel capable of handling production surges of this volume. Describe Area Affected and Cleanup Action Taken. Please see attached Basin Environmental Remediation Summary and Risked-Base Site Closure Request, dated August 2010, for remediation details.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
			1		_1		OIL CONS	ERV	NON	DIVISION		
Signature: Sul Smolow					OIL CONSERVATION DIVISION Signed By M, 14 Samuel							
					Approved by District Supervisor:							
Title: Agent Ap						Approval Date: P 1 3 2010 Expiration Date: P/A						
E-mail Address: Compton@gp2energy.com Co						Conditions of Approval: MA - Find						
Date:8/25/10		Phone: 432-	684-4748						<u> </u>			
~				-			· · · 			2RP-374		