


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

hmlb1030952075

OPERATOR

☒ Initial Report ☐ Final Report

| | | | | |
|-----------------|-------------------------------------|-------|-------------------|-----------------------|
| Name of Company | OXY USA | 16696 | Contact | Kelton Beaird |
| Address | 1502 W. Commerce Carlsbad, NM 88220 | | Telephone No. (O) | 575-628-4100 |
| Facility Name | Lakewood 15-1 | | Facility Type | Oil Well with Battery |

| | | | | | |
|---------------|---------|---------------|--|----------------|------------|
| Surface Owner | Private | Mineral Owner | | Lease No. API: | 3001533574 |
|---------------|---------|---------------|--|----------------|------------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| I | 15 | 19S | 26E | | | | | Eddy |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|-----------------------------|--|------------------|--------|
| Type of Release | Oil and Produced Water | Volume of Release | 54bbls | Volume Recovered | 25bbls |
| Source of Release | Tank Battery | Date and Hour of Occurrence | Date and Hour of Discovery 10-17-10 @ 1 pm | | |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | | If YES, To Whom? Mike Bratcher (Left message and sent e-mail) | | |
| By Whom? | Kelton Beaird (HES-Oxy) | | Date and Hour See above | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | If YES, Volume Impacting the Watercourse. | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Tank Battery corroded and leaked. The tank was emptied and removed from service

Describe Area Affected and Cleanup Action Taken.*

Area affected is inside the containment walls around the battery and a small amount east of the battery in the pasture apprx. 21' X 12'. The area will be delineated and a clean-up plan will be submitted for approval

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Kelton Beaird

Title: HES Specialist

E-mail Address: kelton_beaird@oxy.com

Date: 10-18-10

OIL CONSERVATION DIVISION

Approved by District Supervisor:

NOV 05 2010

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY: 12/6/2010

2RP-464

* Attach Additional Sheets If Necessary