## API#: 30-015-37693

WELL NAME AND NUMBER	Kersey State #5	
	7 <mark>S, R28E, 2310 FSL, 890 FEL</mark>	, Eddy County
OPERATOR Lime Rock Res	sources	
DRILLING CONTRACTOR	United Drilling, Inc.	
		epresentative of the drilling contractor
	well and had conducted deviate	ion test and obtained the following
results:		
Degrees @ Depth	Degrees @ Depth	Degrees @ Depth
1/4° @ 446'		<u> </u>
1/2° @ 1007'		
1/2° @ 1512'		
3/4° @ 2017'		
1° @, 2490'		
3/4° @ 2996'		
1° @ 3495'		
1 1/2° (@, 4448'		
11/2 (5)		
	•	
		***************************************
	***************************************	***
	Drilling Contractor-	UNITED DRILLING, INC.
	D.,,	Xlusu Husriga
	By:	(Luisa Noriega)
		(Luisa Noriega)
	Title:	Assistant Office Manager
Subscribed and sw	orn to before me this 224 da	y of Alwershow, 2010.
		1 10 -1
		Calue Mathe Notary Public Chaues Mew Mexico
		Notary Public
	1 - 11	I'han Hen Mexico
My Commission Expires: /	0/8/12	County State
	-	