


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NMLB/02955494

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, Tx 79701	Telephone No.	(432) 230-0077
Facility Name	RJU Injection Trunk-Line	Facility Type	Trunk-line

Surface Owner:	Federal	Mineral Owner		Lease No. (API #)	30-015-03765
----------------	---------	---------------	--	-------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	17S	29E	660	North	654	East	Eddy

Latitude N 32 47.701° Longitude W 104 03.233°

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release	190 bbls	Volume Recovered	130 bbls
Source of Release	2" Water flood Trunk Line	Date and Hour of Occurrence	04/15/10	Date and Hour of Discovery	04/15/10 12:00 P.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD Terry Gregston - BLM		
By Whom?	Josh Russo	Date and Hour	04/15/10 9:01 P.M.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

The leak was caused by a due to a failure of a newly installed fiber/poly trunk line. The entire line was removed and replaced.

Describe Area Affected and Cleanup Action Taken.\* Of the 190 bbls or produced water released, approximately 130 bbls were recovered with a vacuum truck. Tetra Tech sampled and delineated the site. Upon completion of the delineation, the site was excavated to a maximum depth of 10 feet bgs and backfilled with clean soils.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeff Kindley</i> as agent for COG		OIL CONSERVATION DIVISION	
Printed Name: Jeff Kindley (as agent for COG)		Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: Senior Project Manager		Approval Date: <i>2/16/2011</i>	Expiration Date: <i>N/A</i>
E-mail Address: jeff.kindley@tetrattech.com		Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: 01/28/11 Phone: (432) 682-4559		<i>Final</i>	

\* Attach Additional Sheets If Necessary

2RP-449